



Zakład Produkcji Lemieszki Stankiewicz Sp. J.

ul. Brylantowa 5, 16 - 400 Suwałki

tel/fax 87 5654202, mobile 50208398

NIP 8441658827 Regon 790289000

e-mail : lemieszki@lemieszki.pl

www.lemieszki.pl

PRICES 2024

02.01.2024

The name of the spare part		The symbol	Weight [kg]	Net price EUR
The plough polish OSKAR				
1	The chisel P – opening square	1023/02059/P/K	1,5	5,13
2	The chisel P – openings conical	1023/02059/P/S	1,5	5,13
3	The chisel L – openings conical	1023/02059/L/S	1,5	5,13
4	The chisel 1023/P <small>HARDOX500</small>	102302059/P H500	1,3	9,60
5	The chisel 1023/L <small>HARDOX500</small>	102302059/L H500	1,3	9,60
6	The share 1/S	1023/02053/1	5,5	14,11
7	The share P 8mm <small>HARDOX500</small>	102302053/P-8	4,1	33,16
8	The share P 10mm <small>HARDOX500</small>	102302053/P-10	4,9	38,01
9	The share 1/S fat to the chisel	1023/02053/Gd	6	15,11
10	The share 4/S	1023/02053/4	4,1	10,34
11	The breast of the moldboard P <small>250HB</small>	102302003/P <small>250HB</small>	2,5	10,39
12	The short slade	1023/020081/S	3,5	7,58
13	The long slade	1023/020070/S	4,3	8,34
14	The cutter P	1024/020071/S	3,2	7,93
15	The support of the share	1023/02000/S	1	2,50
16	Moldboard P <small>250HB</small>	1023020040/P <small>250HB</small>	9	30,95
To the plough ATLAS				
1	The chisel 12mm openings conical <input type="radio"/>		1,7	6,71
2	The chisel 12mm openings square <input type="checkbox"/>		1,7	6,71
3	The share 1/S	1101/403000/1	6,5	17,24
4	The share P <small>HARDOX500</small>	11014030001/P	6,4	49,42
5	The share 1/S fat	1101/403000/G	7,5	18,15
6	The share 1/S AT to the chisel	1101/403000/Gd	7,5	18,15
7	The breast of the moldboard P 1024 <small>250HB</small>	1024020030/P <small>250HB</small>	3,3	12,47
8	The short slade	1109/20004/S	3,4	7,53
9	The long slade	1109/30001/S	3,9	8,34
10	The lap	1109/20005/S	1,6	3,99
To the plough AKPIL				
1	The share P 10mm <small>HARDOX500</small>	1023/02053/P-10	4,9	38,01
2	The share L 10mm <small>HARDOX500</small>	1023/02053/L-10	4,9	38,01
3	The share P <small>HARDOX500</small>	1023/02053/Gd/P	6	47,65
4	The share L <small>HARDOX500</small>	1023/02053/Gd/L	6	47,65
5	The share P <small>HARDOX500</small>	LK200105A/P	6,8	53,76
6	The share L <small>HARDOX500</small>	LK200106A/L	6,8	53,76
7	The breast of the moldboard P <small>HARDOX500</small>	303540/P	2,6	21,28
8	The breast of the moldboard P <small>HARDOX500</small>	NPL114-1/P	2,8	22,30
9	The cutter P <small>HARDOX500</small>	AKPIL	2,6	19,57
To the plough STALTECH				
1	The chisel P <small>HARDOX500</small>	do STALTECH	1,4	11,97
2	The share P <small>HARDOX500</small>	do STALTECH	5,6	46,05
3	The breast P <small>HARDOX500</small>	do STALTECH	2,4	19,51
4	The cutter P <small>HARDOX500</small>	do STALTECH	3,2	26,97
5	The slade P <small>HARDOX500</small>	do STALTECH	4,1	28,49
6	The lap P/L <small>HARDOX500</small>	do STALTECH	2,2	16,61

To the plough FAMAROL				
1	The share P/L HARDOX500	11240400001/S	5,9	45,37
2	The share P/L HARDOX500	11250600003/S	5,8	44,60
3	The breast P/L HARDOX500	1125060020/S	1,8	20,27
4	The short slade P/L HARDOX500	11250060045/S	2,2	16,47
To the plough AGROMASZ				
1	The breast P HARDOX500	PL00249/P	1,5	16,50
2	The breast L HARDOX500	PL00248/L	1,5	16,50
3	The short slade P/L 18" HARDOX500	PL00327/S	6,7	48,17
To the plough EUROMASZ				
1	The long slade P/L 20" HARDOX500	long 20"	7,6	53,85
To the plough METAL FACH				
1	The long slade P HARDOX500	U034/P	5,3	37,99
The first ploughing plough				
1	The share 2/S	1025	3,2	8,34
To the plough UNIA				
1	The chisel 12mm right <input type="checkbox"/>	1067911010/12/P	1,6	6,71
2	The chisel P 15mm <input type="checkbox"/>	1067911010/15/P	2,2	8,80
3	The chisel L 15mm <input type="checkbox"/>	1067911010/15/L	2,2	8,80
4	The chisel P HARDOX500 2 opening	1067911010/P	1,7	12,69
5	The chisel L HARDOX500 2 opening	1067921010/L	1,7	12,69
6	The chisel P HARDOX500 3 opening	1067911011/P	1,8	14,59
7	The chisel L HARDOX500 3 opening	1067921011/L	1,8	14,59
8	The chisel P HARDOX500 3 opening	1150712010/P	1,4	11,91
9	The chisel L HARDOX500 3 opening	1150722010/L	1,4	11,91
10	The share 1/S	1126/50500/0/1	5,5	14,11
11	The share 1/S lengthened	1126/505000/1p	6	15,11
12	The share 1/S fat to the chisel	1117511500/Gd	6	15,11
13	The share R HARDOX500	1117/51-150/0/P	6	43,00
14	The share L HARDOX500	1117/61-150/0/L	6	43,00
15	The share R HARDOX500	1150712500/P	6,3	47,49
16	The share L HARDOX500	1150722500/L	6,3	47,49
17	The share R HARDOX500	1067/91-100/0/P	6,8	47,29
18	The share L HARDOX500	1067/92-100/0/L	6,8	47,29
19	The share R HARDOX500	PO1188/P	6,9	54,48
20	The share L HARDOX500	PO1192/L	6,9	54,48
21	The breast P HARDOX500	1036700020/P	2,1	17,74
22	The breast P HARDOX500	1126500030/P	2,1	17,74
23	The breast L HARDOX500	1126600030/L	2,1	17,74
24	The breast P HARDOX500	1150930020/P	1,8	15,71
25	The breast L HARDOX500	1150940020/L	1,8	15,71
26	The breast P HARDOX500	PO1702/P	2,2	18,25
27	The breast L HARDOX500	PO1711/L	2,2	18,25
28	The breast P HARDOX500	1067910020/P	2	16,98
29	The breast L HARDOX500	1067920020/L	2	16,98
30	The breast P HARDOX500	1153210020/P	1,8	17,86
31	The breast L HARDOX500	1153220020/L	1,8	17,86
32	The cutter P HARDOX500	1067910070/P	3,8	32,29
33	The cutter L HARDOX500	1067920040/L	3,8	32,29
34	The cutter P HARDOX500	PO1513/P 1153210060/P	3,2	26,97
35	The cutter L HARDOX500	PO1524/L 1153220050/L	3,2	26,97
36	The short slade P HARDOX500	1067/91-003/0/P	4,1	24,42
37	The short slade L HARDOX500	1067/92-003/0/L	4,1	24,42

38	The long slade P HARDOX500	1067/93-001/0/P	5,1	33,15
39	The long slade L HARDOX500	1067/94-001/0/L	5,1	33,15
40	The short slade P HARDOX500	1116/71-002/0/P	3,6	21,98
41	The short slade L HARDOX500	1116/72-001/0/L	3,6	21,98
42	The long slade P HARDOX500	1116/73-001/0/P	4,4	26,17
43	The long slade L HARDOX500	1116/74-001/0/L	4,4	26,17
44	The long slade P HARDOX500	PO1703/P	6,9	46,12
45	The long slade L HARDOX500	PO1712/L	6,9	46,12
46	The long slade P HARDOX500	PO1879/P	4,1	28,49
47	The long slade L HARDOX500	PO1895/L	4,1	28,49
48	The long slade P HARDOX500	1150930030/P	5,1	34,21
49	The long slade L HARDOX500	1150940030/L	5,1	34,21
50	The back plate of the slade T HARDOX500	1067/93002/0/S	3,6	24,58
51	The lap P HARDOX500	1126/70-002/0/P	1,8	13,18
52	The lap L HARDOX500	1117/81-001/0/L	1,8	13,18
53	The front lap P HARDOX500	1127/21-003/0/P	1,2	9,38
54	The front lap L HARDOX500	1127/22-002/0/L	1,2	9,38
The Meadow plough				
1	The share P HARDOX500		8,4	64,62
To the cultivator KOS				
1	The share P HARDOX500	AP87/P	1,8	14,58
2	The share L HARDOX500	AP88/L	1,8	14,58
3	The central cutter HARDOX500	AP702/S	1,5	15,20
4	The central cutter HARDOX500	173805002/S	1,9	17,74
5	The beak of the coulter HARDOX500	AP701/S	2,7	24,07
6	The beak of the coulter HARDOX500	1738050010/S	2,1	18,05
To the CZECH plough PHX				
1	The share 1/S	40430767/1	5,5	14,11
2	The share P HARDOX500	40430767/P	5,2	41,45
3	The share 1/S fat to the chisel	40430767/Gd	6	15,11
4	The share P fat to the chisel HARDOX500	40430767/PGd	5,7	45,19
5	The share L fat to the chisel HARDOX500	40430767/LGd	5,7	45,19
6	The share 4/S	40430767/4	4,1	10,34
7	The short slade P HARDOX500	40300197/P	3,8	25,85
8	The long slade P HARDOX500	40300167/P	4,6	30,92
To the plough B200, FORTSCHRITT				
1	The share 1/S	1023/020569/1	5,5	14,11
2	The share P HARDOX500	1023020569/P	5,2	41,45
3	The share L HARDOX500	1023020569/L	5,2	41,45
4	The share P fat to the chisel HARDOX500	1023020569/PGd	5,5	43,58
5	The share L fat to the chisel HARDOX500	1023020569/LGd	5,5	43,58
6	The breast P HARDOX500	9210088/P	3,3	22,22
7	The long slade P HARDOX500	9210158/P	4,3	29,40
8	The short slade P HARDOX500	9210171/P	2,2	15,71
9	The long slade P HARDOX500	9210172/P	3,7	25,34
The RUSSIAN PLN plough				
1	The share 1/S	PNC 702	5,5	15,88
2	The share 4/S	PNC 702/4	4,7	11,68
3	The narrow slade HARDOX500	PNC 502	2,5	18,20
4	The wide slade HARDOX500	PLZ 51.501	4,4	30,87
The plough Ukrainian				
1	The chisel	PGC11.409	4,3	13,65
2	The share 1/S 701	PGC01.701	4,5	10,34
3	The wide slade HARDOX500	PGC61.200	5,3	36,74

The plough Belorussian				
1	The share P	ПЛП01.007	3,3	11,62
The plough Yugoslavian				
1	The share 1/S	260937/1	4,2	10,70
2	The share 1/S	260938/1	4,9	12,48
3	The share 1/S	BFS-IMT	5,6	14,49
To the plough KVERNELAND				
1	The chisel P	053090/P	1,5	5,12
2	The chisel L	063090//L	1,5	5,12
3	The chisel P HARDOX500	053090/P B38	1,4	7,81
4	The chisel L HARDOX500	063090//L	1,4	7,81
5	The share P HARDOX500	053085/P	5	39,97
6	The share P HARDOX500	053087/P	5,3	42,35
7	The share P HARDOX500	053088/P	5,9	43,69
8	The share P HARDOX500	053089/P	5,7	43,69
9	The share P HARDOX500	063014/P	5,2	41,33
10	The share L HARDOX500	063017/L	5,2	41,33
11	The share P	063015/S 25	6,8	18,96
12	The share P HARDOX500	063015/P	5,7	43,50
13	The share L HARDOX500	063018/L	5,7	43,50
14	The share P HARDOX500	063016/P	6,7	51,10
15	The share L HARDOX500	063019/L	6,7	51,10
16	The share P HARDOX500	073002/P	5,3	42,39
17	The share L HARDOX500	073003/L	5,3	42,39
18	The share P	073004/P 25	6,8	18,96
19	The share P HARDOX500	073004/P 50	5,8	43,50
20	The share L	073005/L 25	6,8	18,96
21	The share L HARDOX500	073005/L 50	5,8	43,50
22	The share P	073006/P 25	7,9	20,41
23	The share P HARDOX500	073006/P 50	6,5	44,26
24	The share L	073007/L 25	7,9	20,41
25	The share L HARDOX500	073007/L 50	6,5	44,26
26	The share P HARDOX500	073008/P	6,9	54,83
27	The share L HARDOX500	073009/L	6,9	54,83
28	The share P HARDOX500	073056/P	5,7	45,38
29	The share L HARDOX500	073057/L	5,7	45,38
30	The share P HARDOX500	073080/P	6,5	51,66
31	The share L HARDOX500	073081/L	6,5	51,66
32	The skim share P HARDOX500	056873/P	1,1	11,28
33	The skim share L HARDOX500	066873/L	1,1	11,28
34	The skim share P HARDOX500	066868/P	1,5	14,21
35	The skim share L HARDOX500	066869/L	1,5	14,21
36	The breast P HARDOX500	063240/P	1	11,78
37	The breast L HARDOX500	063250/L	1	11,78
38	The breast P	073250/P 25	1,5	6,41
39	The breast P HARDOX500	073250/P	1,4	14,63
40	The breast L	073251/L 25	1,5	6,41
41	The breast L HARDOX500	073251/L	1,4	14,63
42	The breast P	073256/P 25	1,7	7,05
43	The breast P HARDOX500	073256/P	1,6	16,88
44	The breast L	073257/L 25	1,7	7,05
45	The breast L HARDOX500	073257/L	1,6	16,88
46	The breast P HARDOX500	073230/P	1,8	17,10
47	The breast L HARDOX500	073231/L	1,8	17,10

48	The breast P HARDOX500	073241/P	2,5	21,89
49	The breast L HARDOX500	073242/L	2,5	21,89
50	The breast P HARDOX500	073272/P	2,2	19,81
51	The breast L HARDOX500	073273/L	2,2	19,81
52	The cutter P HARDOX500	063300/P 073300/P	3,2	24,69
53	The cutter L HARDOX500	063301/L 073301/L	3,2	24,69
54	The cutter P HARDOX500	053362/P	3,6	27,92
55	Holder P HARDOX400	063310/P	2,2	15,58
56	Holder L HARDOX400	063311/L	2,2	15,58
57	Back slat of moldboard P HARDOX500	053380/P	1,9	13,43
58	Back slat of moldboard P HARDOX500	053387/P	2	13,43
59	Back slat of moldboard L HARDOX500	063388/L	2	13,43
60	Holder of share P HARDOX500	073414/P	0,2	4,56
61	Holder of share L HARDOX500	073415/L	0,2	4,56
62	Knife of share P HARDOX450	073091/P	0,8	13,30
63	Knife of share L HARDOX450	073092/L	0,8	13,30
64	Knife of slade P HARDOX500	073088/P	3,4	28,40
65	Knife of slade L HARDOX500	073089/L	3,4	28,40
66	Knife of slade P HARDOX500	084320/P	3,4	30,70
67	Knife of slade L HARDOX500	084321/L	3,4	30,70
68	The long slade P HARDOX500	053665/P	7,7	53,29
69	The short slade P HARDOX500	053681/P	4,2	29,94
70	The long slade P HARDOX500	053685/P	7,5	51,81
71	The short slade P HARDOX500	053684/P	5,2	36,06
72	The long slade P HARDOX500	053683/P	7,1	49,39
73	The short slade P HARDOX500	063602/P	4,8	33,34
74	The long slade P HARDOX500	063601/P	7,5	51,36
75	The short slade P HARDOX500	063605/P 063615/P	4,3	30,13
76	The short slade L HARDOX500	063606/L 063616/L	4,3	30,13
77	The long slade P HARDOX500	063603/P 063613/P	6,2	43,12
78	The long slade L HARDOX500	063604/L 0636014/L	6,2	43,12
79	Internal slat P HARDOX500	063607/P	3,2	23,32
80	The internal slat P HARDOX500	063608/P	1,8	14,21
81	The internal slat L HARDOX500	063609/L	1,8	14,21
82	The short slade R/L HARDOX500	063610/S	5,5	37,90
83	The long slade R/L HARDOX500	063611/S	8,3	55,09
84	The slade R/L HARDOX500	073600/S	5,4	37,19
85	The short slade P HARDOX500	073600/P	6,5	47,12
86	The short slade L HARDOX500	073601/L	6,5	47,12
87	The long slade P HARDOX500	073604/P	9,3	64,09
88	The long slade L HARDOX500	073605/L	9,3	64,09
89	The short slade R/L HARDOX500	073608/S	5,35	35,94
90	The long slade R/L HARDOX500	073609/S	7,8	48,05
91	The slade R HARDOX500	073612/P	8	55,09
92	The lap R/L HARDOX500	063600A/S	1,4	11,15
93	The lap R/L HARDOX500	063601A/S	3,7	29,27
94	The lap HARDOX500	073614/S	1	8,36
95	Skim mouldboard P HARDOX450	056853/P	1,6	18,05
96	Skim mouldboard P HARDOX450	066880/P	1,4	16,75
97	Skim mouldboard L HARDOX450	066881/L	1,4	16,75
To the ploughing aggregate KVERNELAND				
1	The share P HARDOX500	131124/P	2,1	17,23
2	The share L HARDOX500	131125/L	2,1	17,23
3	The share P HARDOX500	301446/P	2,4	19,05

4	The share L HARDOX500	301447/L	2,4	19,05
	To the plough LEMKEN			
1	The chisel P HARDOX500	3363980/P	1,7	14,19
2	The chisel L HARDOX500	3363981/L	1,7	14,19
3	The chisel P HARDOX500	3363986/P	2	16,20
4	The chisel L HARDOX500	3363987/L	2	16,20
5	The chisel P HARDOX500	3364050/P 3364150/P	2	19,19
6	The chisel L HARDOX500	3364051/L 3364151/L	2	19,19
7	The chisel P HARDOX500	3364054/P	2,1	20,23
8	The chisel L HARDOX500	3364055/L	2,1	20,23
9	The chisel P HARDOX500	3365534/P	1,4	11,97
10	The chisel L HARDOX500	3365535/L	1,4	11,97
11	The chisel P HARDOX500	3365540/P	2,2	17,47
12	The chisel L HARDOX500	3365541/L	2,2	17,47
13	The share P HARDOX500	3353742/P	1,9	16,99
14	The share L HARDOX500	3353743/L	1,9	16,99
15	The share 14" P HARDOX500	3351956/P	2,8	23,49
16	The share 14" L HARDOX500	3351957/L	2,8	23,49
17	The share 16" P HARDOX500	3351958/P	3,8	29,90
18	The share 16" L HARDOX500	3351959/L	3,8	29,90
19	The share P HARDOX500	3352010/P	3,1	26,65
20	The share L HARDOX500	3352011/L	3,1	26,65
21	The share P HARDOX500	3352020/P	3,7	30,47
22	The share L HARDOX500	3352021/L	3,7	30,47
23	The share 18" P HARDOX500	3352030/P	4,1	33,51
24	The share 18" L HARDOX500	3352031/L	4,1	33,51
25	The share 20" P HARDOX500	3352134/P	5,2	41,88
26	The share 20" L HARDOX500	3352135/L	5,2	41,88
27	The share 20" P HARDOX500	3352138/P	5,5	46,07
28	The share 20" L HARDOX500	3352139/L	5,5	46,07
29	The share P HARDOX500	3335032/P	6,6	52,07
30	The share L HARDOX500	3335033/L	6,6	52,07
31	The share P HARDOX500	3335036/P	6,8	53,76
32	The share L HARDOX500	3335037/L	6,8	53,76
33	The share P HARDOX500	3333770/P 3333802/P	4,2	34,27
34	The share L HARDOX500	3333771/L 3333803/L	4,2	34,27
35	The share P HARDOX500	3333804/P	6	47,20
36	The share L HARDOX500	3333805/L	6	47,20
37	The share P HARDOX500	3333810/P	5,3	42,04
38	The share L HARDOX500	3333811/L	5,3	42,04
39	The share P HARDOX500	3333812/P	5,9	46,51
40	The share L HARDOX500	3333813/L	5,9	46,51
41	The share P HARDOX500	3334050/P	5,2	41,18
42	The share L HARDOX500	3334051/L	5,2	41,18
43	The share P HARDOX500	3334056/P	6,2	48,97
44	The share L HARDOX500	3334057/L	6,2	48,97
45	The share P HARDOX500	3333818/P	4,6	36,98
46	The share L HARDOX500	3333819/L	4,6	36,98
47	The share P HARDOX500	3333820/P	5,3	42,29
48	The share L HARDOX500	3333821/L	5,3	42,29
49	The share P HARDOX500	3334024/P	3,3	27,87
50	The skim share P HARDOX500	3363712/P	0,9	10,83
51	The skim share L HARDOX500	3363713/L	0,9	10,83
52	The skim share P HARDOX500	3363714/P	1	10,83

53	The skim share L HARDOX500	3363715/L	1	10,83
54	The skim share P HARDOX500	3363720P	1,1	11,28
55	The skim share L HARDOX500	3363721/L	1,1	11,28
56	The skim share P HARDOX500	3363710/P	1,4	13,68
57	The skim share L HARDOX500	3363711/L	1,4	13,68
58	The skim share P/L HARDOX500	3363724/S	1,7	17,10
59	The breast P HARDOX500	3450498/P	1,7	16,82
60	The breast L HARDOX500	3450499/L	1,7	16,82
61	The breast P HARDOX500	3450520/P	1,9	18,05
62	The breast L HARDOX500	3450521/L	1,9	18,05
63	The breast P HARDOX500	3450522/P	2	19,01
64	The breast L HARDOX500	3450523/L	2	19,01
65	The breast P HARDOX500	3450524/P	2,2	20,27
66	The breast L HARDOX500	3450525/L	2,2	20,27
67	The breast P HARDOX500	3450528/P	1,7	16,75
68	The breast L HARDOX500	3450529/L	1,7	16,75
69	The breast P HARDOX500	3450532/P	2,1	19,00
70	The breast L HARDOX500	3450533/L	2,1	19,00
71	The breast P HARDOX500	3450534/P	2,6	22,22
72	The breast L HARDOX500	3450535/L	2,6	22,22
73	The breast P HARDOX500	3450540/P	2,3	19,90
74	The breast L HARDOX500	3450541/L	2,3	19,90
75	The breast P HARDOX500	3451002/P 3451000/P	2,9	23,69
76	The breast L HARDOX500	3451003/L 3451001/L	2,9	23,69
77	The breast P HARDOX500	3451004/P	2,1	18,81
78	The breast L HARDOX500	3451005/L	2,1	18,81
79	The breast P HARDOX500	3451020/P	3,5	23,55
80	The breast L HARDOX500	3451021/L	3,5	23,55
81	The cutter P HARDOX500	3470834/P	3,8	34,19
82	The cutter L HARDOX500	3470835/L	3,8	34,19
83	The cutter P HARDOX500	3470860/P	3,3	28,87
84	The cutter L HARDOX500	3470861/L	3,3	28,87
85	Back slat of moldboard P HARDOX500	3475288/P	2	13,18
86	Back slat of moldboard L HARDOX500	3475289/L	2	13,18
87	Back slat of moldboard P HARDOX500	3476000/P	1,3	10,14
88	Back slat of moldboard L HARDOX500	3476001/L	1,3	10,14
89	The knife of slade P HARDOX500	3492900/P	2,9	24,46
90	The knife of slade L HARDOX500	3492901/L	2,9	24,46
91	The front slade R HARDOX500	3401900/P	1,1	9,90
92	The front slade L HARDOX500	3401901/P	1,1	9,90
93	The front slade P/L HARDOX500	3401903/S	1	9,60
94	The short slade R/L HARDOX500	3401570/S	3,8	27,41
95	The long slade R/L HARDOX500	3411826/S	5	34,72
96	The short slade R HARDOX500	3401860/P	4,1	29,02
97	The short slade L HARDOX500	3401861/L	4,1	29,02
98	The long slade R HARDOX500	3401870/P	5,7	41,41
99	The long slade L HARDOX500	3401871/L	5,7	41,41
100	The long slade R HARDOX500	3411870/P	7,3	50,72
101	The long slade L HARDOX500	3411871/L	7,3	50,72
102	The slade HARDOX500	3401920/S	2	15,59
103	The short slade R/L HARDOX500	3411500/S	4	28,33
104	The long slade R/L HARDOX500	3411504/S	4,6	32,17
105	The slade R/L HARDOX500	3411450/S	5,5	37,90
106	The high slade R/L HARDOX500	3411508/S	6,2	43,12

107	The high slade R/L HARDOX500	3411460/S	6,9	47,87
108	The slade R/L HARDOX500	3411525/S	6	43,08
109	The lap P/L HARDOX500	3401490/S	2,3	20,06
110	The lap P/L HARDOX500	3401550/S	2,1	18,27
111	Skim mouldboard P HARDOX450	3470540/P	1,4	17,10
112	Skim mouldboard L HARDOX450	3470541/L	1,4	17,10
113	Skim mouldboard P HARDOX450	3470650/P	1,6	18,85
114	Skim mouldboard L HARDOX450	3470651/L	1,6	18,85
To the cultivator LEMKEN				
1	The share P HARDOX500	3374402/P	0,8	9,60
2	The share L HARDOX500	3374403/L	0,8	9,60
3	The share P HARDOX500	3374406/P	1,2	12,67
4	The share L HARDOX500	3374407/L	1,2	12,67
5	The share R HARDOX500	3374416/P	2,2	19,26
6	The share L HARDOX500	3374417/L	2,2	19,26
7	The share R HARDOX500	3374420/P	2,5	21,14
8	The share L HARDOX500	3374421/L	2,5	21,14
9	The central cutter HARDOX500	3374395/S	1,8	18,66
10	The beak of the coulter HARDOX500	3374442/S	2	18,25
11	The beak of the coulter HARDOX500	3374388/S	1,8	16,72
12	The side cutter P HARDOX500	3374398/P	2,4	22,26
13	The side cutter L HARDOX500	3374399/L	2,4	22,26
14	Coulter HARDOX500	3374351/S	5,8	43,96
To the plough OVERUM				
1	The chisel P	72635/P	3,5	26,59
2	The chisel P	74601/P	3,5	23,75
3	The lap P	76601/S	0,7	10,83
4	The chisel P B38	35070/P	2,5	19,75
5	The chisel L B38	35071/L	2,5	19,75
6	The chisel P HARDOX500	35074/P	2,4	19,12
7	The chisel L HARDOX500	35075/L	2,4	19,12
8	The chisel P HARDOX500	80514/P	2,1	26,59
9	The chisel L HARDOX500	80543/L	2,1	26,59
10	The chisel P HARDOX500	84060/P 92206/P	2,2	17,47
11	The chisel L HARDOX500	85143/L 92207/L	2,2	17,47
12	The chisel P HARDOX500	84942/P 95000675/P	2,2	17,47
13	The chisel L HARDOX500	85204/L	2,2	17,47
14	The chisel P HARDOX500	84987/P	1,8	14,62
15	The chisel L HARDOX500	85206/L	1,8	14,62
16	The chisel P HARDOX500	92199/P 92201/P	2,2	17,47
17	The chisel L HARDOX500	92200/L 92202/L	2,2	17,47
18	The chisel P HARDOX500	94608/P	2,2	17,47
19	The chisel L HARDOX500	94609/L	2,2	17,47
20	The chisel P HARDOX500	94610/P	2,2	17,47
21	The chisel L HARDOX500	94611/L	2,2	17,47
22	The chisel P HARDOX500	95002490/P	2,3	18,84
23	The chisel P HARDOX500	95000675/P	2,5	19,89
24	The bracket P HARDOX500	35076/P	1,6	15,36
25	The bracket L HARDOX500	35077/L	1,6	15,36
26	The bracket P HARDOX500	84288/P	3,2	26,86
27	The bracket L HARDOX500	84289/L	3,2	26,86
28	The bracket P HARDOX500	84958/P	2,4	20,89
29	The bracket L HARDOX500	85191/L	2,4	20,89

30	The bracket P HARDOX500	94612/P	1,4	13,43
31	The bracket L HARDOX500	94613/L	1,4	13,43
32	The share R HARDOX500	72632/P	3,8	34,54
33	The share R HARDOX500	72633/P	4	36,46
34	The share R HARDOX500	71345/P	4,4	37,99
35	The share R HARDOX500	74903/P	4	33,16
36	The share L HARDOX500	74904/P	4,2	34,07
37	The share R HARDOX500	80521/P	3,6	29,58
38	The share L HARDOX500	80531/L	3,6	29,58
39	The share R HARDOX500	74605/P	3,7	30,38
40	The share R HARDOX500	80605-02/P 74606/P	6,2	34,05
41	The share L HARDOX500	77605/L	4,2	34,05
42	The share R HARDOX500	74607	4,4	35,64
43	The share R HARDOX500	84069/P	3,6	29,94
44	The share L HARDOX500	84078/L	3,6	29,94
45	The share R HARDOX500	85383/P	4,2	34,19
46	The share L HARDOX500	85381/L	4,2	34,19
47	The share R HARDOX500	85384/P	4,2	35,64
48	The share L HARDOX500	85382/L	4,2	35,64
49	The share R 16" HARDOX500	85004/P	2,2	20,94
50	The share L 16" HARDOX500	85194/L	2,2	20,94
51	The share R 18" HARDOX500	85039/P	2,5	23,04
52	The share L HARDOX500	85195/L	2,5	23,04
53	The share R HARDOX500	92219/P	4,1	33,16
54	The share L HARDOX500	92217/L	4,1	33,16
55	The share R HARDOX500	94598/P	3,4	29,32
56	The share L HARDOX500	94599/L	3,4	29,32
57	The share R HARDOX500	94600/P	4,1	33,16
58	The share L HARDOX500	94601/L	4,1	33,16
59	The share R HARDOX500	94602/P	4,7	38,38
60	The share L HARDOX500	94603/L	4,7	38,38
61	The share R 16" HARDOX500	96090/P	4	32,47
62	The share L 16" HARDOX500	96091/L	4	32,47
63	The share R HARDOX500	96092/P	4,5	36,46
64	The share L HARDOX500	96093/L	4,5	36,46
65	The share R HARDOX500	35040/P	4,7	38,38
66	The share L HARDOX500	35041/L	4,7	38,38
67	The share P HARDOX500	35042/P	5,3	42,29
68	The share L HARDOX500	35043/L	5,3	42,29
69	The share P HARDOX500	35044/P	5,9	46,51
70	The share L HARDOX500	35045/L	5,9	46,51
71	The share P HARDOX500	9500683/P	3,6	28,79
72	The share P HARDOX500	9500684/P	3,8	30,70
73	The share P HARDOX500	95002489/P	3,2	26,86
74	The share P HARDOX500	80644/P	1	10,83
75	The share L HARDOX500	80639/L	1	10,83
76	The share R HARDOX500	91801/P	1,3	13,13
77	The share L HARDOX500	91802/L	1,3	13,13
78	The breast P HARDOX500	35080/P	2,7	22,81
79	The breast L HARDOX500	35081/L	2,7	22,81
80	The breast P HARDOX500	80512/P	2	17,90
81	The breast L HARDOX500	80513/L	2	17,90
82	The breast P HARDOX500	80609/P 74871/P	1,9	18,05
83	The breast L HARDOX500	80609/L	1,9	18,05

84	The breast P HARDOX500	84033/P	2,3	19,95
85	The breast L HARDOX500	84082/L	2,3	19,95
86	The breast P HARDOX500	83980/P	1,7	17,10
87	The breast L HARDOX500	84083/L	1,7	17,10
88	The breast P HARDOX500	94596/P	1,4	15,20
89	The breast L HARDOX500	94597/L	1,4	15,20
90	The breast P HARDOX500	96086/P	2,6	21,87
91	The breast L HARDOX500	96087/L	2,6	21,87
92	The breast P HARDOX500	95002505/P	3	25,08
93	The cutter P HARDOX500	96064/P 83969/P	3,7	29,95
94	The cutter L HARDOX500	96065/L 83968/L	3,7	29,95
95	Holder P HARDOX400	84022/P	1,5	13,30
96	Holder L HARDOX400	84023/L	1,5	13,30
97	Holder P HARDOX400	99627/P 94624/P	1,6	13,68
98	Holder L HARDOX400	99628/L 94625/L	1,6	13,68
99	Back slat of moldboard P HARDOX450	74922/P	1,6	11,40
100	Back slat of moldboard L HARDOX450	80559/L	1,6	11,40
101	The knife of slade P HARDOX450	94622/P	1,2	12,54
102	The knife of slade P HARDOX450	94623/L	1,2	12,54
103	The front slade P HARDOX500	35060/P	1,1	9,40
104	The front slade L HARDOX500	35061/L	1,1	9,40
105	The slade P HARDOX500	95003732/P	1	9,21
106	The slade P HARDOX500	35062/P	6,2	42,63
107	The slade L HARDOX500	35063/L	6,2	42,63
108	The short slade P HARDOX500	57997/P 72577/P	4,4	36,23
109	The long slade P HARDOX500	57998/P	5,8	44,64
110	The slade P HARDOX500	74943/P	3,9	28,79
111	The short slade P HARDOX500	80505/P	4,6	32,62
112	The short slade L HARDOX500	80506/L	4,6	32,62
113	The front slade P HARDOX500	80602/P 74602/P	2,3	17,39
114	The front slade L HARDOX500	80602/L	2,3	17,39
115	The slade P HARDOX500	80601/P 74612/P	2	15,59
116	The slade L HARDOX500	80601/L	2	15,59
117	The short slade P HARDOX500	84239/P	4,3	30,51
118	The short slade L HARDOX500	84243/L	4,3	30,51
119	The long slade P HARDOX500	80603/P 74603/P	5,8	39,70
120	The long slade L HARDOX500	80603/L	5,8	39,70
121	The short slade P HARDOX500	85675/P	4,3	30,39
122	The short slade L HARDOX500	86126/L	4,3	30,39
123	The long slade P HARDOX500	94561/P	5,9	40,84
124	The long slade L HARDOX500	94562/L	5,9	40,84
125	The short slade P HARDOX500	86291/P	4	28,40
126	The short slade L HARDOX500	85578/L	4	28,40
127	The long slade P HARDOX500	94559/P 85202/P	5,5	39,18
128	The long slade L HARDOX500	94560/L 85133/L	5,5	39,18
129	The short slade P HARDOX500	83981/P	3,9	27,62
130	The short slade L HARDOX500	85196/L	3,9	27,62
131	The long slade P HARDOX500	94286/P	4,7	32,64
132	The long slade L HARDOX500	94287/L	4,7	32,64
133	The short slade P HARDOX500	92230/P	4,5	32,76
134	The short slade L HARDOX500	92229/L	4,5	32,76
135	The long slade P HARDOX500	92232/P	5,8	40,54
136	The long slade L HARDOX500	92231/L	5,8	40,54
137	The long slade P HARDOX500	94604/P	5,1	35,39

138	The long slide L HARDOX500	94605/L	5,1	35,39
139	The long slide P HARDOX500	94606/P	4,7	32,65
140	The long slide L HARDOX500	94607/L	4,7	32,65
141	The long slide P HARDOX500	96094/P	5,4	37,19
142	The long slide L HARDOX500	96095/L	5,4	37,19
143	The slide P HARDOX500	95003736/P	3	23,03
144	The lap HARDOX500	94289/S	3	25,07
145	Cover P HARDOX500	92409/P	4,7	32,89
146	Cover L HARDOX500	92509/L	4,7	32,89
147	Skim mouldboard P HARDOX500	74296/P	2,9	26,02
148	Skim mouldboard L HARDOX500	74297/L	2,9	26,02
149	Skim mouldboard P HARDOX450	91803/P	2,1	20,94
150	Skim mouldboard L HARDOX450	91804/L	2,1	20,94
151	Skim mouldboard P HARDOX450	93062/P	1,5	16,15
152	Skim mouldboard L HARDOX450	93061/L	1,5	16,15
To the plough KUHN				
1	The chisel P HARDOX500	622010/P	1,9	16,46
2	The chisel L HARDOX500	622011/L	1,9	16,46
3	The chisel P HARDOX500	622128/P	1,8	14,62
4	The chisel L HARDOX500	622129/L	1,8	14,62
5	The chisel P HARDOX500	622174/P	2	16,07
6	The chisel L HARDOX500	622175/L	2	16,07
7	The chisel P HARDOX500	622180/P	1,7	14,13
8	The chisel L HARDOX500	622181/L	1,7	14,13
9	The share R HARDOX500	620088/P	6,8	53,92
10	The share L HARDOX500	620089/L	6,8	53,92
11	The share R HARDOX500	622134/P	6,7	52,82
12	The share L HARDOX500	622135/L	6,7	52,82
13	The share R HARDOX500	622136/P 622212/P	7,2	56,74
14	The share L HARDOX500	622137/L 622213/L	7,2	56,74
15	The share P HARDOX500	622202/P	7,9	62,55
16	The share L HARDOX500	622203/L	7,9	62,55
17	The share P HARDOX500	622172/P	8	63,32
18	The share L HARDOX500	622173/L	8	63,32
19	The share R HARDOX500	583890/P	6,9	61,78
20	The share L HARDOX500	583891/L	6,9	61,78
21	The share R HARDOX500	583892/P	7,9	69,11
22	The share L HARDOX500	583893/L	7,9	69,11
23	The share P HARDOX500	622140/P	6,8	53,73
24	The share L HARDOX500	622141/L	6,8	53,73
25	The share P HARDOX500	622142/P	7,8	62,55
26	The share L HARDOX500	622143/L	7,8	62,55
27	The share P HARDOX500	625036/P	4,6	36,98
28	The share L HARDOX500	625037/L	4,6	36,98
29	The share P HARDOX500	625102/P	5,6	44,14
30	The share L HARDOX500	625103/L	5,6	44,14
31	The share P HARDOX500	622016/P	4,4	37,04
32	The share L HARDOX500	622017/L	4,4	37,04
33	The skim share P HARDOX500	631106/P	1,1	11,28
34	The skim share L HARDOX500	631107/L	1,1	11,28
35	The skim share P HARDOX500	631100/P	1,4	13,68
36	The skim share L HARDOX500	631101/L	1,4	13,68
37	The skim share P HARDOX500	631108/P	1,4	13,68
38	The skim share L HARDOX500	631109/L	1,4	13,68

39	The skim share P HARDOX500	631102/P	1,2	12,67
40	The skim share L HARDOX500	631103/L	1,2	12,67
41	The skim share P/L HARDOX500	631112/S	1,8	16,72
42	The breast P HARDOX500	1780/P	1,6	16,75
43	The breast L HARDOX500	1790/L	1,6	16,75
44	The breast P HARDOX500	619040/P	1,6	16,75
45	The breast L HARDOX500	619041/L	1,6	16,75
46	The breast P HARDOX500	619060/P	1,5	16,50
47	The breast L HARDOX500	619061/L	1,5	16,50
48	The breast P HARDOX500	619068/P	1,5	16,50
49	The breast L HARDOX500	619069/L	1,5	16,50
50	The breast P HARDOX500	619102/P	1,6	16,75
51	The breast L HARDOX500	619103/L	1,6	16,75
52	The breast P HARDOX500	619120/P 619168/P	2,4	20,94
53	The breast L HARDOX500	619121/L 619169/L	2,4	20,94
54	The breast P HARDOX500	619128/P 619170/P	2,5	21,85
55	The breast L HARDOX500	619129/L 619171/L	2,5	21,85
56	The breast P HARDOX500	619172/P	2,7	23,04
57	The breast L HARDOX500	619173/L	2,7	23,04
58	The breast P HARDOX500	619278/P	2,3	21,97
59	The breast L HARDOX500	619279/L	2,3	21,97
60	The cutter P/L HARDOX500	619159/S	3,4	28,49
61	Back slat of moldboard P/L HARDOX500	648005/S	1,7	11,40
62	Back slat of moldboard P HARDOX500	648102/P	2	13,18
63	Back slat of moldboard L HARDOX500	648103/L	2	13,18
64	The front slade P HARDOX500	223120/P	0,9	8,53
65	The front slade L HARDOX500	223121/L	0,9	8,53
66	The front slade P HARDOX500	279138/P	0,9	8,53
67	The front slade L HARDOX500	279139/L	0,9	8,53
68	The front slade P HARDOX500	761106/P	0,9	8,53
69	The front slade L HARDOX500	761107/L	0,9	8,53
70	The front slade P HARDOX500	761110/P	0,8	8,53
71	The front slade L HARDOX500	761111/L	0,8	8,53
72	The slade P/L HARDOX500	226104/S	4,5	31,91
73	The short slade P HARDOX500	278070/P	3,6	26,10
74	The short slade L HARDOX500	278071/L	3,6	26,10
75	The long slade P HARDOX500	278072/P	5	34,92
76	The long slade L HARDOX500	278073/L	5	34,92
77	The short slade P HARDOX500	278074/P	2,9	21,27
78	The short slade L HARDOX500	278075/L	2,9	21,27
79	The long slade P HARDOX500	278076/P	4,7	32,64
80	The long slade L HARDOX500	278077/L	4,7	32,64
81	The long slade P HARDOX500	279130/P	4,8	33,34
82	The long slade L HARDOX500	279131/L	4,8	33,34
83	The short slade P HARDOX500	279028/P	1,2	10,57
84	The short slade L HARDOX500	279029/L	1,2	10,57
85	The long slade P HARDOX500	279030/P	3,9	27,62
86	The long slade L HARDOX500	279031/L	3,9	27,62
87	The long slade P HARDOX500	279114/P	5,8	40,27
88	The long slade L HARDOX500	279115/L	5,8	40,27
89	The long slade P HARDOX500	279126/P	2,9	21,27
90	The long slade L HARDOX500	279127/L	2,9	21,27
91	The slade P/L HARDOX500	279140/S	5,4	37,19
92	The slade P/L HARDOX500	761108/S	4,6	32,17

93	The lap P/L HARDOX500	279140A/S	1,5	13,30
94	Skim mouldboard P HARDOX450	618104/P	2	21,15
95	Skim mouldboard L HARDOX450	618105/L	2	21,15
96	Skim mouldboard P HARDOX450	618114/P	1,5	17,10
97	Skim mouldboard L HARDOX450	618115/L	1,5	17,10
98	Skim mouldboard P HARDOX450	619126/P	2,4	23,46
99	Skim mouldboard L HARDOX450	619127/L	2,4	23,46
To the plough RABEWERK				
1	The chisel P HARDOX500	MP293/P	1,6	13,41
2	The chisel L HARDOX500	MP293/L	1,6	13,41
3	The chisel P HARDOX500	MP332/P	1,3	11,24
4	The chisel L HARDOX500	MP332/L	1,3	11,24
5	The chisel P HARDOX500	MP350/P	1,3	11,24
6	The chisel L HARDOX500	MP350/L	1,3	11,24
7	The share P HARDOX500	SSPNB/P	4,1	33,37
8	The share L HARDOX500	SSPNB/L	4,1	33,37
9	The share P HARDOX500	SSP160MB/P	3,3	27,20
10	The share L HARDOX500	SSP160MB/L	3,3	27,20
11	The share P HARDOX500	SSP214/P	4,6	37,23
12	The share L HARDOX500	SSP214/L	4,6	37,23
13	The share P HARDOX500	SSP280/P	7,2	57,57
14	The share L HARDOX500	SSP280/L	7,2	57,57
15	The share P HARDOX500	SSP295OEP/P	7,8	61,75
16	The share L HARDOX500	SSP295OEP/L	7,8	61,75
17	The share P HARDOX500	SSP293OSE/P	7	55,16
18	The share L HARDOX500	SSP293OSE/P	7	55,16
19	The share P HARDOX500	SSP294OSE/P	8	63,09
20	The share L HARDOX500	SSP294OSE/L	8	63,09
21	The share P HARDOX500	SSP200JB/P	4,2	34,27
22	The share L HARDOX500	SSP200JB/L	4,2	34,27
23	The share P HARDOX500	SSP332OS/P	5	39,91
24	The share L HARDOX500	SSP332OS/L	5	39,91
25	The share P HARDOX500	SSP333OS/P	6	47,97
26	The share L HARDOX500	SSP333OS/L	6	47,97
27	The share P HARDOX500	SSP350WE/P	7,5	59,56
28	The share L HARDOX500	SSP350WE/L	7,5	59,56
29	The share P HARDOX500	SSP351/P	8,2	64,89
30	The share L HARDOX500	SSP351/L	8,2	64,89
31	The share P HARDOX500	SSP350W/P	6,8	53,49
32	The share L HARDOX500	SSP350W/L	6,8	53,49
33	The share P HARDOX500	SSP351WSE/P	8,1	64,54
34	The share L HARDOX500	SSP351WSE/L	8,1	64,54
35	The share P HARDOX500	27230401/P	6,8	53,49
36	The share L HARDOX500	27230402/L	6,8	53,49
37	The share P HARDOX500	27150101/P	0,9	10,83
38	The share L HARDOX500	27150102/L	0,9	10,83
39	The share P HARDOX500	SDG18B/P	1,4	13,68
40	The share L HARDOX500	SDG18B/L	1,4	13,68
41	The share P HARDOX500	SDG12B/P	0,8	10,14
42	The share L HARDOX500	SDG12B/L	0,8	10,14
43	The share P HARDOX500	SDG14/16/P	1	10,85
44	The share L HARDOX500	SDG14/16/L	1	10,85
45	The breast P HARDOX500	VRP290/P	2,4	22,07
46	The breast L HARDOX500	VRP290/L	2,4	22,07

47	The breast P HARDOX500	VRP2920/P	1,7	17,82
48	The breast L HARDOX500	VRP2920/L	1,7	17,82
49	The breast P HARDOX500	VRP2300/P	1,9	17,82
50	The breast L HARDOX500	VRP2300/L	1,9	17,82
51	The breast P HARDOX450	VRP300/P	1,8	17,93
52	The breast L HARDOX450	VRP300/L	1,8	17,93
53	The breast P HARDOX500	VRP300T/P	1,1	12,92
54	The breast L HARDOX500	VRP300T/L	1,1	12,92
55	The breast P HARDOX500	VRP320/P	1,8	17,93
56	The breast L HARDOX500	VRP320/L	1,8	17,93
57	The breast P HARDOX500	VRP330/P	2	18,85
58	The breast L HARDOX500	VRP330/L	2	18,85
59	The breast P HARDOX500	VRP340/P	2	18,85
60	The breast L HARDOX500	VRP340/L	2	18,85
61	The breast P HARDOX500	VRP342R/P	1,9	18,24
62	The breast L HARDOX500	VRP342R/L	1,9	18,24
63	The breast P HARDOX500	VRP350W/P	2,1	19,90
64	The breast L HARDOX500	VRP350W/L	2,1	19,90
65	The cutter P HARDOX500	27290101/P	4,5	39,79
66	The cutter L HARDOX500	27290102/L	4,5	39,79
67	The cutter P HARDOX500	27300101/P	4	37,04
68	The cutter L HARDOX500	27300102/L	4	37,04
69	Holder P HARDOX400	27290701/P EBP4/P	2,6	49,39
70	Holder L HARDOX400	27290702/L EBP4/L	2,6	49,39
71	Back slat of moldboard P HARDOX500	27011801/P	2,2	14,19
72	Back slat of moldboard L HARDOX500	27011802/L	2,2	14,19
73	The front slade R HARDOX500	27510205/P	1,2	10,57
74	The front slade L HARDOX500	27510205/L	1,2	10,57
75	The front slade R/L HARDOX500	27600601/S	0,9	9,60
76	The front slade R/L HARDOX500	27532005/S	0,6	7,60
77	The short slade P HARDOX500	27011500/P	3,5	25,16
78	The short slade L HARDOX500	27011500/L	3,5	25,16
79	The long slade P HARDOX500	27011400/P	5,6	38,57
80	The long slade L HARDOX500	27011400/L	5,6	38,57
81	The short slade P HARDOX500	27011700/P	3,3	24,18
82	The short slade L HARDOX500	27011700/L	3,3	24,18
83	The long slade P HARDOX500	27011600/P	5,3	36,84
84	The long slade L HARDOX500	27011600/L	5,3	36,84
85	The short slade P HARDOX500	27080702/P	2,5	19,90
86	The short slade L HARDOX500	27080702/L	2,5	19,90
87	The long slade P HARDOX500	27080701/P	4	29,32
88	The long slade L HARDOX500	27080701/L	4	29,32
89	The short slade P HARDOX500	27080704/P	2,4	18,42
90	The short slade L HARDOX500	27080704/L	2,4	18,42
91	The long slade P HARDOX500	27080703/P	3,7	26,86
92	The long slade L HARDOX500	27080703/L	3,7	26,86
93	The long slade P HARDOX500	27240401/P	4,2	29,94
94	The long slade L HARDOX500	27240401/L	4,2	29,94
95	The short slade P HARDOX500	27340902/P	3,9	28,02
96	The short slade L HARDOX500	27340902/L	3,9	28,02
97	The long slade P HARDOX500	27340901/P	5,6	39,15
98	The long slade L HARDOX500	27340901/L	5,6	39,15
99	The short slade P HARDOX500	27360902/P	4,7	33,01
100	The short slade L HARDOX500	27360902/L	4,7	33,01

101	The long slide P HARDOX500	27360901/P	7,4	51,04
102	The long slide L HARDOX500	27360901/L	7,4	51,04
103	The short slide P HARDOX500	27371602/P	3,5	25,71
104	The short slide L HARDOX500	27371602/L	3,5	25,71
105	The long slide P HARDOX500	27371601/P	5,4	37,61
106	The long slide L HARDOX500	27371601/L	5,4	37,61
107	The short slide P HARDOX500	27480603/P	2,2	16,71
108	The short slide L HARDOX500	27480604/L	2,2	16,71
109	The long slide P HARDOX500	27480601/P	3,3	24,18
110	The long slide L HARDOX500	27480602/L	3,3	24,18
111	The short slide P/L HARDOX500	27510306/S	3,7	26,28
112	The long slide P/L HARDOX500	27510305/S	6,2	42,42
113	The long slide P HARDOX500	27520900/P	8	54,88
114	The long slide L HARDOX500	27520900/L	8	54,88
115	The short slide P HARDOX500	27530502/P	2,3	17,39
116	The short slide L HARDOX500	27530504/L	2,3	17,39
117	The long slide P/L HARDOX500	WP3000/S	3,9	27,62
118	The short slide P HARDOX500	27991101/P	3	21,87
119	The short slide L HARDOX500	27991102/L	3	21,87
120	The long slide P HARDOX500	27991105/P	4,1	29,17
121	The long slide L HARDOX500	27991106/L	4,1	29,17
122	The lap R/L HARDOX500	27081400/S	3,4	24,45
123	The lap R/L HARDOX500	27081401/S	5	34,92
124	The lap R/L HARDOX500	27081500/S	1,1	9,90
125	The lap R HARDOX500	27521801/P	8,6	59,10
126	The lap L HARDOX500	27521801/L	8,6	59,10
127	Skim mouldboard P HARDOX450	27150801/P	2	20,94
128	Skim mouldboard L HARDOX450	27150802/L	2	20,94
To the Aggregate RABE				
1	The share R HARDOX500	63361604/P	0,9	9,61
2	The share L HARDOX500	63361603/L	0,9	9,61
3	The share R HARDOX500	63421212/P	1,1	11,51
4	The share L HARDOX500	63421211/L	1,1	11,51
5	The share R HARDOX500	63425004/P	1,2	12,57
6	The share L HARDOX500	63425003/L	1,2	12,57
7	The share R HARDOX500	63425006/P	1,5	14,59
8	The share L HARDOX500	63425005/L	1,5	14,59
9	The share R HARDOX500	63425010/P	1,5	14,59
10	The share L HARDOX500	63425009/L	1,5	14,59
To the plough NIEMEYER				
1	The chisel P HARDOX500	24104/P	1,2	10,75
2	The chisel L HARDOX500	24105/L	1,2	10,75
3	The chisel P HARDOX500	200610/P	1,6	13,40
4	The chisel L HARDOX500	200611/L	1,6	13,40
5	The chisel P HARDOX500	200678/P	2,2	20,93
6	The chisel L HARDOX500	200679/L	2,2	20,93
7	The share P HARDOX500	24102/P	4	33,43
8	The share L HARDOX500	24103/L	4	33,43
9	The share P HARDOX500	24122/P	5	43,08
10	The share L HARDOX500	24121/L	5	43,08
11	The share P HARDOX500	200414/P	5,9	47,02
12	The share L HARDOX500	200415/L	5,9	47,02
13	The share P HARDOX500	200614/P	6	47,30
14	The share L HARDOX500	200615/L	6	47,30

15	The share P HARDOX500	200814/P	6,1	48,15
16	The share L HARDOX500	200815/L	6,1	48,15
17	The share P HARDOX500	200616/P	6,3	49,75
18	The share L HARDOX500	200617/L	6,3	49,75
19	The share P HARDOX500	200830/P	6,5	51,33
20	The share L HARDOX500	200829/L	6,5	51,33
21	The share P HARDOX500	200810/P	7,4	58,39
22	The share L HARDOX500	200811/L	7,4	58,39
23	The share P HARDOX500	200626/P	6,4	50,54
24	The share L HARDOX500	200625/L	6,4	50,54
25	The skim share P HARDOX500	26018/P	1,1	11,13
26	The skim share L HARDOX500	26017/L	1,1	11,13
27	The skim share P HARDOX500	26088/P	1,1	11,13
28	The skim share L HARDOX500	26087/L	1,1	11,13
29	The skim share P HARDOX500	26104/P	1,4	13,68
30	The skim share L HARDOX500	26103/L	1,4	13,68
31	The breast P HARDOX500	20536/P	2,1	18,85
32	The breast L HARDOX500	20535/L	2,1	18,85
33	The breast P HARDOX500	20736/P	2,6	21,85
34	The breast L HARDOX500	20735/L	2,6	21,85
35	The breast P HARDOX500	23436/P	2,7	23,04
36	The breast L HARDOX500	23435/L	2,7	23,04
37	The breast P HARDOX500	24080/P	2,7	23,04
38	The breast L HARDOX500	24081/L	2,7	23,04
39	The breast P HARDOX500	24114/P	2,1	18,66
40	The breast L HARDOX500	24113/L	2,1	18,66
41	The breast P HARDOX500	200648/P	3,4	28,27
42	The breast L HARDOX500	200649/L	3,4	28,27
43	The cutter P HARDOX500	26180/P	3,8	32,29
44	The cutter L HARDOX500	26181/L	3,8	32,29
45	Back slat of moldboard P/L HARDOX500	26105/S	0,6	6,65
46	The front slade R HARDOX500	24004/P	1,1	9,90
47	The front slade L HARDOX500	24004/L	1,1	9,90
48	The front slade R HARDOX500	24013/P	1,7	13,54
49	The front slade L HARDOX500	24013/L	1,7	13,54
50	The slade P/L HARDOX500	24072/S	5,2	36,06
51	The short slade P HARDOX500	20016/P	3,3	23,78
52	The short slade L HARDOX500	20015/L	3,3	23,78
53	The long slade P HARDOX500	20018/P	4,1	29,04
54	The long slade L HARDOX500	20017/L	4,1	29,04
55	The short slade P HARDOX500	20620/P	4,1	29,00
56	The short slade L HARDOX500	20619/L	4,1	29,00
57	The long slade P HARDOX500	20622/P	5,1	35,39
58	The long slade L HARDOX500	20621/L	5,1	35,39
59	The short slade P HARDOX500	21416/P	4,3	31,41
60	The short slade L HARDOX500	21415/L	4,3	31,41
61	The long slade P HARDOX500	21328/P	6,1	42,93
62	The long slade L HARDOX500	21327/L	6,1	42,93
63	The short slade P HARDOX500	21916/P	5,4	37,61
64	The short slade L HARDOX500	21915/L	5,4	37,61
65	The long slade P HARDOX500	21928/P	6,8	46,82
66	The long slade L HARDOX500	21927/L	6,8	46,82
67	The short slade P/L HARDOX500	23416/S	4,6	32,62
68	The long slade P/L HARDOX500	23428/S	7,1	48,74

To the plough **GASSNER**

1	The share P	HARDOX500	SS1080/P	4,8	38,32
2	The share L	HARDOX500	SS1090/L	4,8	38,32
3	The share P	HARDOX500	SS1180/P	5	39,91
4	The share L	HARDOX500	SS1190/L	5	39,91
5	The share P	HARDOX500	MS1080/P	4,9	39,38
6	The share L	HARDOX500	MS1090/L	4,9	39,38
7	The share P	HARDOX500	SS1100/P	5,3	42,32
8	The share L	HARDOX500	SS1110/L	5,3	42,32
9	The share P	HARDOX500	SS1140/P	5,4	42,63
10	The share L	HARDOX500	SS1150/L	5,4	42,63
11	The share P	HARDOX500	MS1100/P	5,3	42,21
12	The share L	HARDOX500	MS1110/L	5,3	42,21
13	The share P	HARDOX500	MSS11384/P	6	47,30
14	The share L	HARDOX500	MSS11385/L	6	47,30
15	The share P	HARDOX500	MS1140/P	5,6	44,42
16	The share L	HARDOX500	MS1150/L	5,6	44,42
17	The share P	HARDOX500	GM162/P	6,4	50,66
18	The share L	HARDOX500	GM162/L	6,4	50,66
19	The share P	HARDOX500	MS13018/P	5,3	42,10
20	The share L	HARDOX500	MS13019/L	5,3	42,10
21	The share P	HARDOX500	MRSS1580/P	6	47,59
22	The share L	HARDOX500	MRSS1590/L	6	47,59
23	The share P	HARDOX500	FR2/P	1	10,85
24	The share L	HARDOX500	FR2/L	1	10,85
25	The breast P	HARDOX500	VST1060/P	1,2	13,82
26	The breast L	HARDOX500	VST1070/L	1,2	13,82
27	The breast P	HARDOX500	VST1080/P	1,4	14,82
28	The breast L	HARDOX500	VST1090/L	1,4	14,82
29	The breast P	HARDOX500	VST1120/P	1,6	15,73
30	The breast L	HARDOX500	VST1130/L	1,6	15,73
31	The breast P	HARDOX500	VST1160/P	1,7	16,96
32	The breast L	HARDOX500	VST1170/L	1,7	16,96
33	The breast P	HARDOX500	VST1360/P	1,7	16,96
34	The breast L	HARDOX500	VST1370/L	1,7	16,96
35	The breast P	HARDOX500	VST1380/P	1,8	17,93
36	The breast L	HARDOX450	VST1390/L	1,8	17,93
37	Back slat of moldboard P	HARDOX500	96662/P	2	13,18
38	Back slat of moldboard L	HARDOX500	96663/L	2	13,18
39	The short slade P	HARDOX500	L1083/Pk	4,1	29,00
40	The short slade L	HARDOX500	L1093/Lk	4,1	29,00
41	The long slade P	HARDOX500	L1083/Pd	5,3	37,04
42	The long slade L	HARDOX500	L1093/Ld	5,3	37,04
43	The long slade P	HARDOX500	L1123/P	5,7	40,75
44	The long slade L	HARDOX500	L1133/L	5,7	40,75
45	The long slade P/L	HARDOX500	L1582/S	3	22,79

To the plough **VOGEL NOOT**

1	The chisel P	HARDOX500	PK8/P 801101/P	1,4	12,17
2	The chisel L	HARDOX500	PK8/L 801102/L	1,4	12,17
3	The share P	HARDOX500	5000103/P	3,8	30,92
4	The share L	HARDOX500	5000203/L	3,8	30,92
5	The share P	HARDOX500	PK000003/P	5,4	42,82
6	The share L	HARDOX500	PK000004/L	5,4	42,82
7	The share P	HARDOX500	PK000005/P	5,7	45,02

8	The share L HARDOX500	PK000006/L	5,7	45,02
9	The share P HARDOX500	PK000007/P	6	47,51
10	The share L HARDOX500	PK000008/L	6	47,51
11	The share P HARDOX500	601301/P	5,5	43,59
12	The share L HARDOX500	601401/L	5,5	43,59
13	The share P HARDOX500	701301/P	5,9	46,69
14	The share L HARDOX500	701401/L	5,9	46,69
15	The share P HARDOX500	801301/P	6,3	49,89
16	The share L HARDOX500	801401/L	6,3	49,89
17	The share P HARDOX500	400101/P	6,2	49,34
18	The share L HARDOX500	400201/L	6,2	49,34
19	The share P HARDOX500	401301/P	6,1	48,10
20	The share L HARDOX500	401401/L	6,1	48,10
21	The share P HARDOX500	9103001/P	5,8	45,75
22	The share L HARDOX500	9103101/L	5,8	45,75
23	The share P HARDOX500	9303002/P	5,1	40,69
24	The share L HARDOX500	9303102/L	5,1	40,69
25	The share P HARDOX500	305401/P	1,1	11,28
26	The share L HARDOX500	305501/L	1,1	11,28
27	The share P HARDOX500	135601/P	1,7	17,10
28	The share L HARDOX500	135701/L	1,7	17,10
29	The share P HARDOX500	667001/P	1,2	12,67
30	The share L HARDOX500	667004/L	1,2	12,67
31	The breast P HARDOX500	300103/P	1,6	16,13
32	The breast L HARDOX500	300203/L	1,6	16,13
33	The breast P HARDOX500	400103/P	1,6	16,13
34	The breast L HARDOX500	400203/L	1,6	16,13
35	The breast P HARDOX500	600500/P	1	16,75
36	The breast L HARDOX500	600600/L	1	16,75
37	The breast P HARDOX500	800501/P	2,2	19,90
38	The breast L HARDOX500	800601/L	2,2	19,90
39	The breast P HARDOX500	900105/P	2,9	24,08
40	The breast L HARDOX500	900205/L	2,9	24,08
41	The cutter P HARDOX500	105102/P	3	25,64
42	The cutter L HARDOX500	105202/L	3	25,64
43	Back slat of moldboard P/L HARDOX500	700102/S	1	8,87
44	Back slat of moldboard P HARDOX500	800102/P	1,4	10,64
45	Back slat of moldboard L HARDOX500	800202/L	1,4	10,64
46	Knife of slade P HARDOX500	201901/P	3,7	31,34
47	Knife of slade L HARDOX500	202001/L	3,7	31,34
48	The slade R HARDOX500	813003/P	2,5	19,57
49	The slade L HARDOX500	814003/L	2,5	19,57
50	The slade R HARDOX500	913003/P	2,3	17,24
51	The slade L HARDOX500	914003/L	2,3	17,24
52	The short slade P/L HARDOX500	703003/S	2,8	20,56
53	The long slade P/L HARDOX500	703002/S	4,9	34,02
54	The short slade P HARDOX500	103401/P	8,2	56,99
55	The short slade L HARDOX500	103501/L	8,2	56,99
56	The long slade P HARDOX500	103601/P	12	82,15
57	The long slade L HARDOX500	103701/L	12	82,15
58	The short slade P HARDOX500	5000301/P	2,5	19,19
59	The short slade L HARDOX500	5000401/L	2,5	19,19
60	The long slade P HARDOX500	5000105/P	4,5	31,50
61	The long slade L HARDOX500	5000205/L	4,5	31,50

62	The short slide P HARDOX500	803401/P	4,2	29,67
63	The short slide L HARDOX500	803501/L	4,2	29,67
64	The short slide P HARDOX500	8903401/P	3,4	24,45
65	The short slide L HARDOX500	8903501/L	3,4	24,45
66	The long slide P HARDOX500	8903601/P	5,7	38,99
67	The long slide L HARDOX500	8903701/L	5,7	38,99
68	The slide P/L HARDOX500	5800901/S	5	39,41
69	The slide HARDOX500	5801101/S	3,3	27,16
70	The lap P/L HARDOX500	703001/S	1,2	10,64
71	Skim mouldboard P HARDOX450	136602/P	1,8	19,58
72	Skim mouldboard L HARDOX450	136702/L	1,8	19,58
73	Skim mouldboard P HARDOX450	137602/P	2,7	24,65
74	Skim mouldboard L HARDOX450	137702/L	2,7	24,65
75	Skim mouldboard P HARDOX450	Z2335603/P	0,9	12,35
76	Skim mouldboard L HARDOX450	Z2335703/L	0,9	12,35
To the cultivator VOGEL NOOT				
1	The share R HARDOX500	92536/P	1	10,25
2	The share L HARDOX500	92537/L	1	10,25
To the plough KRONE				
1	The chisel P HARDOX500	9290990/P	1,1	10,03
2	The chisel L HARDOX500	9291990/L	1,1	10,03
3	The chisel P HARDOX500	9690990/P	1,2	10,75
4	The chisel L HARDOX500	9691990/L	1,2	10,75
5	The chisel P HARDOX500	9690980/P	1,4	12,21
6	The chisel L HARDOX500	9691980/L	1,4	12,21
7	The share P HARDOX500	929015/P	3,5	28,83
8	The share L HARDOX500	929115/L	3,5	28,83
9	The share P HARDOX500	969003/P 929003/P	4,9	39,11
10	The share L HARDOX500	969103/L	4,9	39,11
11	The share P HARDOX500	969005/P	5,3	42,29
12	The share L HARDOX500	969105/L	5,3	42,29
13	The share R HARDOX500	969007/P	5,8	46,05
14	The share L HARDOX500	969107/L	5,8	46,05
15	The share R HARDOX500	969009/P	6,3	49,84
16	The share L HARDOX500	969109/L	6,3	49,84
17	The share R HARDOX500	969021/P 929036/P	5,1	43,86
18	The share L HARDOX500	969121/L 929136/L	5,1	43,86
19	The share P HARDOX500	969029/P	6,2	48,89
20	The share L HARDOX500	969129/L	6,2	48,89
21	The share P HARDOX500	969095/P	5,4	42,98
22	The share L HARDOX500	969195/L	5,4	42,98
23	The share P HARDOX500	969096/P	5,9	46,82
24	The share L HARDOX500	969196/L	5,9	46,82
25	The share R/L HARDOX500	9691971/S	6,1	48,10
26	The share R HARDOX500	9690911/P	0,9	10,83
27	The share L HARDOX500	9691911/L	0,9	10,83
28	The share R HARDOX500	969092/P	1,3	13,43
29	The share L HARDOX500	969192/L	1,3	13,43
30	The breast P HARDOX500	929413/P	2,4	20,78
31	The breast L HARDOX500	929433/L	2,4	20,78
32	The breast P HARDOX500	959400/P	2	19,01
33	The breast L HARDOX500	959420/L	2	19,01
34	The breast P HARDOX500	959403/P	2	19,01
35	The breast L HARDOX500	959423/L	2	19,01

36	The breast P HARDOX500	959405/P 969405/P	2,1	19,51
37	The breast L HARDOX500	959425/L 969425/L	2,1	19,51
38	The breast P HARDOX500	959407/P	2,2	20,27
39	The breast L HARDOX500	959427/L	2,2	20,27
40	The breast P HARDOX500	959415/P	2,1	19,51
41	The breast L HARDOX500	959435/L	2,1	19,51
42	The front slade R HARDOX500	123166/P	1,3	11,03
43	The front slade L HARDOX500	123112/L	1,3	11,03
44	The slade P HARDOX500	4651292/P	3	23,31
45	The slade L HARDOX500	4651292/L	3	23,31
46	The short slade P HARDOX500	BKG8/Pk	2,6	20,38
47	The long slade P HARDOX500	BKG8/Pd	3,2	23,51
48	The short slade P HARDOX500	123029/P	2,3	17,65
49	The short slade L HARDOX500	123159/L	2,3	17,65
50	The long slade P HARDOX500	123160/P	4,2	29,74
51	The long slade L HARDOX500	123161/L	4,2	29,74
52	The long slade P HARDOX500	123162/P	5	34,92
53	The long slade L HARDOX500	123163/L	5	34,92
54	The long slade P HARDOX500	123164/P	5,9	40,68
55	The long slade L HARDOX500	123165/L	5,9	40,68
56	Skim mouldboard P HARDOX450	VD141/P	1,2	15,20
57	Skim mouldboard L HARDOX450	VD141/L	1,2	15,20
58	Mouldboard P HARDOX450	BKG8/P	5,1	43,69
59	Mouldboard P/L HARDOX500	123722/S	15,9	114,49
To the plough LANDSBERG				
1	The chisel P HARDOX500	41662/P	2,5	20,89
2	The chisel L HARDOX500	41663/L	2,5	20,89
3	The chisel P B38	41856/P	2,5	20,89
4	The chisel L B38	41857/L	2,5	20,89
5	The chisel P HARDOX500	1903675/P	1,1	10,03
6	The chisel L HARDOX500	1903676/L	1,1	10,03
7	The share R HARDOX500	1903684/P	3,4	28,00
8	The share L HARDOX500	1903685/L	3,4	28,00
9	The share R HARDOX500	1903686/P	4	32,89
10	The share L HARDOX500	1903687/L	4	32,89
11	The share R HARDOX500	1903946/P	4,5	36,46
12	The share L HARDOX500	1903947/L	4,5	36,46
13	The share R HARDOX500	1902680/P	3,9	31,72
14	The share L HARDOX500	1902690/L	3,9	31,72
15	The share R HARDOX500	1903020/P	4,6	36,98
16	The share L HARDOX500	1903030/L	4,6	36,98
17	The share R HARDOX500	1902740/P	5	39,91
18	The share L HARDOX500	1902750/L	5	39,91
19	The share R HARDOX500	1903654/P	5,5	43,63
20	The share L HARDOX500	1903655/L	5,5	43,63
21	The share R HARDOX500	1903671/P	5,3	41,05
22	The share L HARDOX500	1903672/L	5,3	41,05
23	The share R HARDOX500	1903673/P	5,8	46,10
24	The share L HARDOX500	1903674/L	5,8	46,10
25	The share R HARDOX500	1847Z/P	1,5	14,59
26	The share L HARDOX500	1848Z/L	1,5	14,59
27	The share R HARDOX500	1903693/P	1,9	18,05
28	The share L HARDOX500	1903694/L	1,9	18,05
29	The share R HARDOX500	1903695/P	1,3	13,13

30	The share L HARDOX500	1903696/L	1,3	13,13
31	The breast P HARDOX500	1765Z/P	1,6	17,22
32	The breast L HARDOX500	1766Z/L	1,6	17,22
33	The breast P HARDOX500	41584Z/P	2,1	19,95
34	The breast L HARDOX500	41585Z/L	2,1	19,95
35	The breast P HARDOX500	41617A/P	1,8	18,50
36	The breast L HARDOX500	41618A/L	1,8	18,50
37	The breast P HARDOX500	41623A/P	2,7	24,07
38	The breast L HARDOX500	41624A/L	2,7	24,07
39	The breast P HARDOX500	41884/P	2,4	21,65
40	The breast L HARDOX500	41885/L	2,4	21,65
41	The breast P HARDOX500	1903524/P	2,1	19,95
42	The breast L HARDOX500	1903525/L	2,1	19,95
43	The cutter P HARDOX500	33097/P P261/P	3,5	29,43
44	The cutter L HARDOX500	33098/L P261/L	3,5	29,43
45	The cutter P HARDOX500	33156/P	2,9	24,69
46	The cutter L HARDOX500	33157/L	2,9	24,69
47	Holder P HARDOX400	P26/P	1,5	13,30
48	Holder L HARDOX400	P26/L	1,5	13,30
49	Back slat of moldboard P HARDOX500	41538Z/P	1,3	10,39
50	Back slat of moldboard L HARDOX500	41539Z/L	1,3	10,39
51	The slade P HARDOX500	805Z/P	4,5	32,94
52	The slade L HARDOX500	806Z/L	4,5	32,94
53	The short slade P HARDOX500	1499Z/P	5,1	37,62
54	The short slade L HARDOX500	1500Z/L	5,1	37,62
55	The long slade P HARDOX500	1497Z/P	6,4	45,61
56	The long slade L HARDOX500	1498Z/L	6,4	45,61
57	The slade P HARDOX500	41816Z/P 41869Z/P	5,2	38,52
58	The slade L HARDOX500	41816Z/L 41869Z/L	5,2	38,52
59	The lap P/L HARDOX500	41793Z/S	3,1	24,58
60	The leg HARDOX500	Stupica Servo1	7,4	96,55
To the plough ROWER				
1	The chisel P HARDOX500	702120/P	2	16,05
2	The chisel L HARDOX500	702121/L	2	16,05
3	The share P HARDOX500	702122/P	2,1	18,47
4	The share L HARDOX500	702123/L	2,1	18,47
5	The share R HARDOX500	N558/P	3,6	29,84
6	The share R HARDOX500	N258/P	4,9	39,07
7	The share R HARDOX500	N158/P	7,2	56,79
8	The breast P HARDOX450	702948/P	1,7	16,47
9	The short slade P HARDOX500	N256/P	2,9	21,49
To the plough GREGOIRE BESSON				
1	The chisel P/L HARDOX500	171207/S	5,3	45,59
2	The chisel 12 mm HARDOX500	173332/P	1,7	14,13
3	The chisel 12 mm HARDOX500	173331/L	1,7	14,13
4	The chisel P HARDOX500	177328/P	1,6	13,96
5	The chisel L HARDOX500	177327/L	1,6	13,96
6	The share P HARDOX500	172402/P 172418/P	4,5	36,46
7	The share L HARDOX500	172401/L 172417/L	4,5	36,46
8	The share P HARDOX500	172614/P	5,2	41,81
9	The share L HARDOX500	172613/L	5,2	41,81
10	The share P HARDOX500	173410/P	6,1	48,25
11	The share L HARDOX500	173409/L	6,1	48,25
12	The share P HARDOX500	173424/P	5,1	40,69

13	The share L HARDOX500	173423/L	5,1	40,69
14	The share P HARDOX500	173610/P	6,6	52,07
15	The share L HARDOX500	173609/L	6,6	52,07
16	The share P HARDOX500	173614/P 178126/P 177602/P	5,7	44,94
17	The share L HARDOX500	173613/L 178125/L 177601/L	5,7	44,94
18	The share P HARDOX500	173802/P	6,5	51,72
19	The share L HARDOX500	173801/L	6,5	51,72
20	The share P HARDOX500	19114/P	0,9	10,83
21	The share L HARDOX500	19113/L	0,9	10,83
22	The share P HARDOX500	19126/P	1,4	13,68
23	The share L HARDOX500	19125/L	1,4	13,68
24	The breast P HARDOX500	173322/P	2,3	21,97
25	The breast L HARDOX500	173321/L	2,3	21,97
26	The breast P HARDOX500	173336/P	2,5	23,21
27	The breast L HARDOX500	173335/L	2,5	23,21
28	The breast P HARDOX500	173340/P	2	19,51
29	The breast L HARDOX500	173339/L	2	19,51
30	The breast P HARDOX500	173346/P	2,2	19,90
31	The breast L HARDOX500	173345/L	2,2	19,90
32	The breast P HARDOX500	173476/P	2,1	20,27
33	The breast L HARDOX500	173475/L	2,1	20,27
34	The breast P HARDOX500	177428/P	2,1	20,27
35	The breast L HARDOX500	177429/L	2,1	20,27
36	The breast P HARDOX500	178114/P	3,8	30,41
37	The breast L HARDOX500	178113/L	3,8	30,41
38	The cutter P HARDOX500	19303/P	3,7	31,34
39	The cutter L HARDOX500	19304/L	3,7	31,34
40	Holder P HARDOX500	19301/P	2,2	16,47
41	Holder L HARDOX500	19302/L	2,2	16,47
42	Back slat of moldboard P HARDOX500	172312/P	1,8	12,67
43	Back slat of moldboard L HARDOX500	172311/L	1,8	12,67
44	The short slade P/L HARDOX500	172338/S	2,6	19,73
45	The long slade P HARDOX500	172380/P	5	39,02
46	The long slade L HARDOX500	172380/L	5	39,02
47	The short slade P HARDOX500	173334/P 173338/P	2,5	19,01
48	The short slade L HARDOX500	173333/L 173337/L	2,5	19,01
49	The long slade P/L HARDOX500	173387/S	5,2	36,46
50	The long slade P HARDOX500	173388/P	4,9	34,02
51	The long slade L HARDOX500	173388/L	4,9	34,02
52	The slade P/L HARDOX500	177312/S	5,7	40,54
53	The long slade P HARDOX500	177319/P	5,1	36,05
54	The long slade L HARDOX500	177319/L	5,1	36,05
55	The long slade P HARDOX500	177MOL/P	7,5	53,29
56	The long slade L HARDOX500	177MOL/L	7,5	53,29
57	The lap S HARDOX500	177349/S	2,9	24,18
58	The lap P HARDOX500	172380A/P	2,9	24,18
59	The lap L HARDOX500	172380A/L	2,9	24,18
To the plough EBERHARDT				
1	The chisel P HARDOX500	302490/P 300336/P	2,2	17,44
2	The chisel L HARDOX500	302491/L 300335/L	2,2	17,44
3	The share P HARDOX500	54550/P	5,6	44,14
4	The share L HARDOX500	54551/L	5,6	44,14
5	The share P HARDOX500	54560/P	5,2	42,21

6	The share L	HARDOX500	54561/L	5,2	42,21
7	The share P	HARDOX500	54564/P	5,2	42,21
8	The share L	HARDOX500	54565/L	5,2	42,21
9	The share P	HARDOX500	302488/P	3,1	25,86
10	The share L	HARDOX500	302487/L	3,1	25,86
11	The share P	HARDOX500	306196/P	5,2	42,21
12	The share L	HARDOX500	306195/L	5,2	42,21
13	The share P	HARDOX500	22602/P	1	11,51
14	The share L	HARDOX500	22603/L	1	11,51
15	The breast P	HARDOX500	STB40000/P	2,1	19,95
16	The breast L	HARDOX500	STB40001/L	2,1	19,95
17	The short slade P	HARDOX500	110210/P	3	21,98
18	The short slade L	HARDOX500	110211/L	3	21,98
19	The long slade P	HARDOX500	110222/P	5,6	38,61
20	The long slade L	HARDOX500	110223/L	5,6	38,61
21	The slade P/L	HARDOX500	301162/S	4	28,42
To the plough FROST					
1	The chisel P	HARDOX500	50612/P	2,2	17,47
2	The chisel L	HARDOX500	50613/L	2,2	17,47
3	The share P	HARDOX500	50618/P	3,7	35,23
4	The share L	HARDOX500	50619/L	3,7	35,23
5	The share P	HARDOX500	50587/P	5	39,91
6	The share L	HARDOX500	50588/L	5	39,91
7	The share P	HARDOX500	50589/P	5,6	44,42
8	The share L	HARDOX500	50590/L	5,6	44,42
9	The share P	HARDOX500	51769/P	9,1	73,10
10	The share L	HARDOX500	51770/L	9,1	73,10
11	The share P	HARDOX500	50614/P	5,9	51,24
12	The share L	HARDOX500	50615/L	5,9	51,24
13	The share P	HARDOX500	50602/P	1,3	13,13
14	The share L	HARDOX500	50603/L	1,3	13,13
15	The share P	HARDOX500	50604/P	1,3	10,14
16	The share L	HARDOX500	50605/L	1,3	10,14
17	The breast P	HARDOX500	50552/P	1,2	13,94
18	The breast L	HARDOX500	50553/L	1,2	13,94
19	The breast P	HARDOX500	51148/P	2,8	24,07
20	The breast L	HARDOX500	51149/L	2,8	24,07
21	The breast P	HARDOX500	51154/P	2,7	23,76
22	The breast L	HARDOX500	51155/L	2,7	23,76
23	Back slat of moldboard P	HARDOX450	51201/P	2,5	16,15
24	Back slat of moldboard L	HARDOX450	51202/L	2,5	16,15
25	The slade P	HARDOX500	51213/P	1,6	13,11
26	The slade L	HARDOX500	51214/L	1,6	13,11
27	The slade P	HARDOX500	51205/P	4,8	33,43
28	The slade L	HARDOX500	51206/L	4,8	33,43
29	The slade P	HARDOX500	51207/P	4,8	33,43
30	The slade L	HARDOX500	51208/L	4,8	33,43
31	The slade P	HARDOX500	51209/P	4,2	30,39
32	The slade L	HARDOX500	51210/L	4,2	30,39
33	The slade P	HARDOX500	51211/P	5,6	42,74
34	The slade L	HARDOX500	51212/L	5,6	42,74
35	The lap P/L	HARDOX500	311000/S	2,8	22,81
To the cultivator FROST					
1	The share P	HARDOX500	51542/P	2	18,62

2	The share L HARDOX500	51543/L	2	18,62
3	The share P HARDOX500	51749/P 51842/P	1,8	16,72
4	The share L HARDOX500	51750/L 51843/L	1,8	16,72
5	The share P HARDOX500	51834/P	2,2	20,52
6	The share L HARDOX500	51835/L	2,2	20,52
To the plough POTTINGER				
1	The chisel P HARDOX500	925130111/P	2,8	21,35
2	The chisel L HARDOX500	925130211/L	2,8	21,35
3	The chisel P HARDOX500	925260110/P	2,8	21,35
4	The chisel L HARDOX500	925260210/L	2,8	21,35
5	The chisel P HARDOX500	930201250/P	1,8	14,65
6	The chisel L HARDOX500	930211250/L	1,8	14,65
7	The chisel P HARDOX500	930701260/P	1,4	12,16
8	The chisel L HARDOX500	930711260/L	1,4	12,16
9	The chisel P B38	930761270/P	1,6	13,61
10	The chisel L HARDOX500	930771270/L	1,6	13,61
11	The share P HARDOX500	925131161/P	5,2	41,48
12	The share L HARDOX500	925131261/L	5,2	41,48
13	The share P HARDOX500	925260131/P	6,2	48,89
14	The share L HARDOX500	925260231/L	6,2	48,89
15	The share P HARDOX500	930401200/P	7,2	57,18
16	The share L HARDOX500	930411200/L	7,2	57,18
17	The share P HARDOX500	930762210/P	5,6	44,52
18	The share L HARDOX500	930772210/L	5,6	44,52
19	The share P HARDOX500	930761210/P	6,5	51,81
20	The share L HARDOX500	930771210/L	6,5	51,81
21	The share P HARDOX500	930781221/P	6,8	53,73
22	The share L HARDOX500	930791220/L	6,8	53,73
23	The share P HARDOX500	921052250/P	1,2	12,67
24	The share L HARDOX500	921062250/L	1,2	12,67
25	The share P HARDOX500	921021480/P	1,4	13,68
26	The share L HARDOX500	921021580/L	1,4	13,68
27	The breast P HARDOX500	928500250/P	2,4	21,54
28	The breast L HARDOX500	928510250/L	2,4	21,54
29	The breast P HARDOX500	930760350/P 930760370/P 930780363/P 930770350/L	2,5	22,05
30	The breast L HARDOX500	930770370/L 930790363/L	2,5	22,05
31	The breast P HARDOX500	930821350/P	2,9	24,07
32	The breast L HARDOX500	930831350/L	2,9	24,07
33	The cutter P HARDOX500	930740100/P	3,5	29,44
34	The cutter L HARDOX500	930750100/L	3,5	29,44
35	The slade P HARDOX500	929100001/P	1	10,14
36	The slade L HARDOX500	929100050/L	1	10,14
37	The slade P HARDOX500	929101000/P	1,5	12,54
38	The slade L HARDOX500	929101050/L	1,5	12,54
39	The slade P HARDOX500	930700050/P	2	15,54
40	The slade L HARDOX500	930710050/L	2	15,54
41	The slade P HARDOX500	930760051/P	2,2	16,61
42	The slade L HARDOX500	930770051/L	2,2	16,61
43	The slade P HARDOX500	930780050/P	1,9	15,01
44	The slade L HARDOX500	930790050/L	1,9	15,01
45	The slade P HARDOX500	930821150/P	2,4	17,87
46	The slade L HARDOX500	930831150/L	2,4	17,87
47	The slade P/L HARDOX500	902950050/S	2,6	20,27
48	The slade P/L HARDOX500	902950250/S	4,1	30,70

49	The slade P/L	HARDOX500	940950050/S	6	42,21
50	The slade P/L	HARDOX500	940950250/S	3,6	26,86
51	The slade P/L	HARDOX500	929100101/S	5,9	40,68
52	The slade P/L	HARDOX500	929100201/S	4,3	34,54
53	The slade P/L	HARDOX500	929100210/S	7	55,26
To the cultivator POTTINGER					
1	The share R	HARDOX500	939502201/P	1,3	12,61
2	The share L	HARDOX500	939502211/L	1,3	12,61
3	The share R	HARDOX500	966500310/P	2,3	20,27
4	The share L	HARDOX500	966500210/L	2,3	20,27
To the plough FRAUGDE					
1	The share P	HARDOX500	93136/P	5,3	54,14
2	The share L	HARDOX500	93137/L	5,3	54,14
3	The share P	HARDOX500	93138/P	5,5	56,99
4	The share L	HARDOX500	93139/L	5,5	56,99
5	The share P	HARDOX500	93114/P	6,8	53,73
6	The share L	HARDOX500	93115/L	6,8	53,73
7	The long slade P	HARDOX500	93600/P	8,5	58,62
8	The long slade L	HARDOX500	93601/L	8,5	58,62
9	The long slade P	HARDOX500	93635/P	5,3	36,77
10	The long slade L	HARDOX500	93636/L	5,3	36,77
11	The long slade P	HARDOX500	93650/P	4,2	30,39
12	The long slade L	HARDOX500	93651/L	4,2	30,39
To the plough HOWARD					
1	The share P/L	HARDOX500	187314/S	7,5	58,89
2	The share P/L	HARDOX500	8211125/S	7	55,09
3	The breast P/L	HARDOX450	187051/S	1	25,34
4	The short slade P/L	HARDOX500	8211125/Sk	2,2	16,47
5	The long slade P/L	HARDOX500	8211125/Sd	3,3	24,07
6	Mouldboard P/L	HARDOX500	60017/S	14,2	105,97
To the plough DIN					
1	The chisel welded P	HARDOX500	18035005/P	0,5	5,03
2	The chisel welded L	HARDOX500	18035006/L	0,5	5,03
3	The share R	HARDOX500	384/P	3,2	26,75
4	The share L	HARDOX500	384/L	3,2	26,75
5	The share R	HARDOX500	436/P	3,5	28,83
6	The share L	HARDOX500	436/L	3,5	28,83
To the plough SKJOLD					
1	The chisel P	HARDOX500	90060185/P	2	15,47
2	The chisel L	HARDOX500	90060189/L	2	15,47
3	The chisel P	HARDOX500	90062090/P	3,1	28,64
4	The chisel L	HARDOX500	90062091/L	3,1	28,64
5	The bracket P	HARDOX500	90062104/P	2,5	23,21
6	The bracket L	HARDOX500	90062109/L	2,5	23,21
7	The bracket P	HARDOX500	90242010/P	2,1	19,98
8	The bracket L	HARDOX500	90242011/L	2,1	19,98
9	The share R	HARDOX500	90060001/P	6,5	53,89
10	The share L	HARDOX500	90060051/L	6,5	53,89
11	The share R	HARDOX500	90060002/P	7,4	61,35
12	The share R	HARDOX500	90060004/P	3,5	28,79
13	The share L	HARDOX500	90060054/L	3,5	28,79
14	The share R	HARDOX500	90060005/P	4,5	37,30
15	The share L	HARDOX500	90060055/L	4,5	37,30
16	The share R	HARDOX500	90060354/P	3,7	32,62

17	The share L HARDOX500	90060355/L	3,7	32,62
18	The share R HARDOX500	90062106/P	2,6	29,01
19	The share L HARDOX500	90062108/L	2,6	29,01
20	The head of the share R HARDOX500	90060184/P	1,2	10,62
21	The head of the share L HARDOX500	90060188/L	1,2	10,62
22	The share R HARDOX500	90898061/P	1,3	13,13
23	The share L HARDOX500	90898062/L	1,3	13,13
24	The breast P HARDOX500	90060332/P	4,9	38,38
25	The breast L HARDOX500	90060333/L	4,9	38,38
26	The breast P HARDOX500	90063161/P	2,4	22,64
27	The breast L HARDOX500	90063170/L	2,4	22,64
28	Back slat of moldboard P HARDOX450	23485/P	2,2	14,25
29	Back slat of moldboard L HARDOX450	23486/L	2,2	14,25
30	The short slade P HARDOX500	90063102/P	5,1	35,39
31	The short slade L HARDOX500	90063008/L	5,1	35,39
32	The long slade P HARDOX500	90063103/P	6,8	48,27
33	The long slade L HARDOX500	90063009/L	6,8	48,27
34	The short slade P/L HARDOX500	90230020/S	2,8	23,03
35	The slade P/L HARDOX500	90060347/S	4,1	29,02
36	The long slade P/L HARDOX500	90060348/S	5,4	38,38
37	The lap P/L HARDOX500	90060349/S	1,3	12,35
38	The lap P/L HARDOX500	90063163/S	2,8	22,81
To the plough VENTZKI				
1	The share P HARDOX500	405101/P	2,8	23,53
2	The share L HARDOX500	405102/L	2,8	23,53
3	The share P HARDOX500	406001/P	2,9	24,32
4	The share L HARDOX500	406002/L	2,9	24,32
5	The share P HARDOX500	7422000/P	0,7	9,21
6	The share L HARDOX500	7422001/L	0,7	9,21
7	The short slade P HARDOX500	384125/P	2,5	18,81
8	The short slade L HARDOX500	384126/L	2,5	18,81
9	The long slade P HARDOX500	384291/P	3	21,94
10	The long slade L HARDOX500	384292/L	3	21,94
11	The long slade P HARDOX500	384293/P	3,7	26,65
12	The long slade L HARDOX500	384294/L	3,7	26,65
To the plough NAUD				
1	The chisel P HARDOX500	3054502/P	2	16,07
2	The chisel L HARDOX500	3054502/L	2	16,07
3	The share R HARDOX500	3054452/P	6,5	55,97
4	The share L HARDOX500	3054452/L	6,5	55,97
5	The share R HARDOX500	31187D/P	7,4	73,76
6	The share L HARDOX500	31187D/L	7,4	73,76
7	The share R HARDOX500	4032101/P	0,9	10,83
8	The share L HARDOX500	4032101/L	0,9	10,83
9	The share R HARDOX500	4032104/P	1,3	13,13
10	The share L HARDOX500	4032104/L	1,3	13,13
11	The slade P/L HARDOX500	3065201/S	2,5	18,81
12	The slade P/L HARDOX500	3065501/S	3,7	26,97
13	The slade P/L HARDOX500	3065101/S	4,5	31,76
14	Skim mouldboard P HARDOX450	4022101/P	1,5	17,10
15	Skim mouldboard L HARDOX450	4022101/L	1,5	17,10
To the plough REGENT				
1	The chisel P B38	3318601/P	2,1	16,79
2	The chisel L B38	3318602/L	2,1	16,79

3	The chisel P B38	DSG500/P	2	19,01
4	The chisel L B38	DSG500/L	2	19,01
5	The share R HARDOX500	DU35S/P	5,1	40,70
6	The share L HARDOX500	DU35S/L	5,1	40,70
7	The share R HARDOX500	DW35S/P	5,4	43,08
8	The share L HARDOX500	DW35S/L	5,4	43,08
9	The share R HARDOX500	DU433S/P	5,1	40,71
10	The share L HARDOX500	DU433S/L	5,1	40,71
11	The share R HARDOX500	DU435S/P	5,4	43,08
12	The share L HARDOX500	DU435S/L	5,4	43,08
13	The share R HARDOX500	DW435S/P	5,4	43,08
14	The share L HARDOX500	DW435S/L	5,4	43,08
15	The share R HARDOX500	3318671/P	6,4	50,54
16	The share L HARDOX500	3318672/L	6,4	50,54
17	The share R HARDOX500	DG540/P	3	28,38
18	The share L HARDOX500	DG540/L	3	28,38
19	The share R HARDOX500	DG545/P	3,7	31,68
20	The share R HARDOX500	3327196/P	1,2	12,67
21	The share L HARDOX500	3327164/L	1,2	12,67
22	The short slade P HARDOX500	16001181/P	3,7	26,75
23	The short slade L HARDOX500	16001182/L	3,7	26,75
24	The long slade P HARDOX500	16002121/P	4,2	29,70
25	The long slade L HARDOX500	16002122/L	4,2	29,70
26	The short slade P HARDOX500	43201151/P	4,4	32,62
27	The short slade L HARDOX500	43201152/P	4,4	32,62
28	The long slade P HARDOX500	17002111/P	6,3	43,37
29	The long slade L HARDOX500	17002112/P	6,3	43,37
30	The slade P HARDOX500	93640251/P	5,3	37,04
31	The slade L HARDOX500	93640252/L	5,3	37,04
32	The lap HARDOX500	1600220/S	2,5	20,27
33	The lap HARDOX500	1700221/S	4,2	29,78
To the plough BRIX				
1	The chisel P HARDOX500	415256/P	1,4	11,97
2	The chisel L HARDOX500	415300/L	1,4	11,97
3	The share R HARDOX500	405127/P	6,6	52,07
4	The share L HARDOX500	405128/L	6,6	52,07
5	The share P HARDOX500	400742/P	1	10,83
6	The share L HARDOX500	415309/L	1	10,83
7	The breast P HARDOX500	405103/P	3,4	27,87
8	The breast L HARDOX500	405104/L	3,4	27,87
9	The breast P HARDOX500	401263/P	1,7	17,27
10	The breast L HARDOX500	415308/L	1,7	17,27
11	The long slade P HARDOX500	400542/P	7,5	54,48
12	The slade P HARDOX500	415284/P	6,6	45,97
13	The slade L HARDOX500	415301/L	6,6	45,97
14	The lap HARDOX500	415163/S	1,5	13,30
15	The lap HARDOX500	415164/S	3,3	24,87
To the plough FENET				
1	The chisel P HARDOX500	do FENET	1,6	12,91
2	The chisel L HARDOX500	do FENET	1,6	12,91
3	The share R HARDOX500	23052/P	4,5	37,99
4	The share L HARDOX500	23053/L	4,5	37,99
5	The share R HARDOX500	2145/P	5,3	45,59
6	The share L HARDOX500	2146/L	5,3	45,59

7	The short slide P	HARDOX500	8100/P	3,4	27,87
8	The short slide L	HARDOX500	8101/L	3,4	27,87
9	The long slide P	HARDOX500	8102/P	3,8	30,41
10	The long slide L	HARDOX500	8103/L	3,8	30,41
To the plough INTERNATIONAL					
1	The chisel P	HARDOX500	1867673/P	1,3	11,24
2	The chisel L	HARDOX500	1867672/L	1,3	11,24
3	The share R	HARDOX500	1867679/P 2214/P	5	42,21
4	The share L	HARDOX500	1867678/L 2215/L	5	42,21
5	The short slide P	HARDOX500	316093/Pk	2,5	21,11
6	The short slide L	HARDOX500	737559/Lk	2,5	21,11
7	The long slide P	HARDOX500	316093/Pd	3,5	27,87
8	The long slide L	HARDOX500	737559/Ld	3,5	27,87
To the plough SOUCHU PINET					
1	The share P	HARDOX500	1186/P 1867675/P	6,2	51,81
2	The share L	HARDOX500	1187/L 1867674/L	6,2	51,81
3	The share P	HARDOX500	2756/P	1,1	11,28
4	The share L	HARDOX500	2755/L	1,1	11,28
5	The short slide P	HARDOX500	k/P	4,7	34,72
6	The short slide L	HARDOX500	k/L	4,7	34,72
7	The long slide P	HARDOX500	d/P	7,2	51,17
8	The long slide L	HARDOX500	d/L	7,2	51,17
To the plough RUMPTSTAD					
1	The chisel P	HARDOX500	18102/P	2,4	19,19
2	The chisel L	HARDOX500	18101/L	2,4	19,19
3	The chisel P	HARDOX500	18136/P	2,6	21,89
4	The chisel L	HARDOX500	18135/L	2,6	21,89
5	The share P	HARDOX500	18104/P	4,3	36,46
6	The share L	HARDOX500	18103/L	4,3	36,46
7	The share P	HARDOX500	18122/P	4,9	39,65
8	The share L	HARDOX500	18121/L	4,9	39,65
9	The share P	HARDOX500	18106/P	5,4	44,35
10	The share L	HARDOX500	18105/L	5,4	44,35
11	The share P	HARDOX500	18118/P	4	34,21
12	The share L	HARDOX500	18117/L	4	34,21
13	The share P	HARDOX500	1210/P	7,4	59,55
14	The share L	HARDOX500	1209/L	7,4	59,55
15	The share P	HARDOX500	0227/P	5,5	46,05
16	The share P	HARDOX500	0354/P	1,3	13,43
17	The share L	HARDOX500	0351/L	1,3	13,43
18	The breast P	HARDOX500	RS28008/P	5,1	39,28
19	The breast L	HARDOX500	RS28007/L	5,1	39,28
20	The short slide P	HARDOX500	RS20544/Pk	6	43,59
21	The short slide L	HARDOX500	RS20545Pk	6	43,59
22	The long slide P	HARDOX500	RS20544/Pd	7,9	55,75
23	The long slide L	HARDOX500	RS20545/Pd	7,9	55,75
To the plough DURO					
1	The chisel P	HARDOX500	6432/P	1,6	13,40
2	The chisel L	HARDOX500	6431/L	1,6	13,40
3	The share R	HARDOX500	6429/P	7,6	64,58
4	The share L	HARDOX500	6430/L	7,6	64,58
5	The breast P	HARDOX500	5954/P	1,7	16,75
6	The breast L	HARDOX500	5955/L	1,7	16,75
7	The breast P	HARDOX500	6920/P	1,8	17,80

8	The breast L HARDOX500	6921/L	1,8	17,80
To the plough MASCHIO Gaspardo				
1	The share R HARDOX500	A51908100R/P	6	47,64
2	The share L HARDOX500	A51908110R/L	6	47,64
3	The short slade P/L HARDOX500	64000044/S	4	28,79
4	The long slade P/L HARDOX500	64000045/S	5	35,31
To the plough KYLLINGSTAD				
1	The share P HARDOX500	400512/P	6,5	56,42
2	The share P HARDOX500	400514/P	7,5	67,61
3	The share P HARDOX500	401222/P	2,6	23,03
4	The share P HARDOX500	415084/P	3,8	31,68
To the plough STEENO				
1	The chisel P HARDOX500	30340002/P	3	36,88
2	The chisel L HARDOX500	30340001/L	3	36,88
3	The chisel P HARDOX500	30340006/P	2,4	18,81
4	The chisel L HARDOX500	30340005/L	2,4	18,81
5	The share R HARDOX500	24017801/P	2,1	19,19
6	The share L HARDOX500	24017802/L	2,1	19,19
7	The share R HARDOX500	24064502/P	2,9	25,59
8	The share L HARDOX500	24064501/L	2,9	25,59
9	The share R HARDOX500	24064504/P	3,8	30,92
10	The share L HARDOX500	24064503/L	3,8	30,92
11	The share R HARDOX500	30340026/P	2,9	25,59
12	The share L HARDOX500	30340025/L	2,9	25,59
13	The share R HARDOX500	15002002/P	1,9	19,19
14	The share L HARDOX500	15002001/L	1,9	19,19
15	The front slade P HARDOX500	24061925/P	1	9,98
16	The front slade L HARDOX500	24061926/L	1	9,98
17	The front slade P HARDOX500	24061902/P	1,4	12,79
18	The front slade L HARDOX500	24061901/L	1,4	12,79
19	The front slade P HARDOX500	24061924/P	1,6	14,63
20	The front slade L HARDOX500	24061923/L	1,6	14,63
21	The short slade P HARDOX500	24061912/P	1,3	12,35
22	The short slade L HARDOX500	24061911/L	1,3	12,35
23	The long slade P HARDOX500	24061916/P	1,7	15,35
24	The long slade L HARDOX500	24061915/L	1,7	15,35
25	The short slade P HARDOX500	24061914/P	1,8	15,35
26	The short slade L HARDOX500	24061913/L	1,8	15,35
27	The long slade P HARDOX500	24061918/P	2,2	19,19
28	The long slade L HARDOX500	24061917/L	2,2	19,19
29	The slade P/L HARDOX500	24064101/S 24064104/S	5,3	38,38
To the plough DOWDESWELL				
1	The chisel P HARDOX500	1176598/P	1,3	11,40
2	The chisel L HARDOX500	1176599/L	1,3	11,40
3	The chisel P HARDOX500	147298/P	2,5	19,54
4	The chisel L HARDOX500	147299/L	2,5	19,54
5	The chisel P B38	309798/P	1,3	11,40
6	The chisel L B38	309799/L	1,3	11,40
7	The share P HARDOX500	147898/P	1,8	17,74
8	The share L HARDOX500	147899/L	1,8	17,74
9	The share P HARDOX500	269798/P	2,2	21,54
10	The share L HARDOX500	269799/L	2,2	21,54
11	The share P HARDOX500	1115398/P	3,5	31,68
12	The share L HARDOX500	1115399/L	3,5	31,68

13	The share P	HARDOX500	1138398/P	5,8	48,15
14	The share L	HARDOX500	1138399/L	5,8	48,15
15	The share R	HARDOX450	48098/P	1,2	12,67
16	The share L	HARDOX450	48099/L	1,2	12,67
17	The breast P	HARDOX500	1462298/P	1,6	17,48
18	The breast L	HARDOX500	1462299/L	1,6	17,48
19	The breast P	HARDOX500	1462498/P	1,6	17,48
20	The breast L	HARDOX500	1462499/L	1,6	17,48
21	The breast P	HARDOX500	900649/P	1,5	16,47
22	The breast L	HARDOX500	900650/L	1,5	16,47
23	Back slat of moldboard P	HARDOX500	900642/P	1,9	13,18
24	Back slat of moldboard L	HARDOX500	900641/L	1,9	13,18
25	The slade P	HARDOX500	SCN1032/P	3,9	28,49
26	The slade L	HARDOX500	SCN1031/L	3,9	28,49
27	The slade P	HARDOX500	1018898/P	4,4	32,89
28	The slade L	HARDOX500	1018899/L	4,4	32,89
29	The slade P/L	HARDOX500	1136700/S	5,8	40,54
30	The slade P	HARDOX500	1137498/P	7,5	53,73
31	The slade L	HARDOX500	1137499/L	7,5	53,73
32	The slade P/L	HARDOX500	164700/S 164798/S	4,1	30,01
33	The slade P/L	HARDOX500	164898/S	6,4	46,05
34	The lap P/L	HARDOX500	902121/S	2,8	22,13
To the plough SUKOV					
1	The share R	HARDOX500	Junior /P	3,6	30,70
2	The share L	HARDOX500	Junior /L	3,6	30,70
3	The share R	HARDOX500	SR30/P	4,5	36,74
4	The share L	HARDOX500	SR30/L	4,5	36,74
5	The share R	HARDOX500	KV09/P	6,8	53,78
6	The share L	HARDOX500	KV09/L	6,8	53,78
7	The breast P	HARDOX500	122201/P	2,1	19,19
8	The breast L	HARDOX500	122202/L	2,1	19,19
9	The cutter P	HARDOX500	18220110/P	4	36,09
10	The cutter L	HARDOX500	29220110/L	4	36,09
11	The slade P	HARDOX500	KV09/Pp	1,7	13,94
12	The slade L	HARDOX500	KV09/Lp	1,7	13,94
13	The long slade P	HARDOX500	KV09/Pd	3,9	28,79
14	The long slade L	HARDOX500	KV09/Ld	3,9	28,79
15	The slade P	HARDOX500	Sukov3	6,4	45,61
16	The slade L	HARDOX500	Sukov4	6,4	45,61
To the plough BOVLUND					
1	The chisel P	HARDOX500	16617/P	2,6	20,24
2	The chisel L	HARDOX500	16667/L	2,6	20,24
3	The share R	HARDOX500	16616/P	3,6	30,70
4	The share L	HARDOX500	16666/L	3,6	30,70
5	The long slade P	HARDOX500	16630/P	8,6	59,49
6	The long slade L	HARDOX500	16680/L	8,6	59,49
To the plough BUGNOT					
1	The chisel P	HARDOX500	6012B/P	1,5	12,55
2	The chisel L	HARDOX500	6013B/L	1,5	12,55
3	The share P	HARDOX500	6014B/P	5,6	44,14
4	The share L	HARDOX500	6015B/L	5,6	44,14
5	The share P	HARDOX500	6026B/P 6028B/P	6,8	55,32
6	The share L	HARDOX500	6027B/L 6029B/L	6,8	55,32
7	The share P	HARDOX500	5116/P	1	10,97

8	The share L HARDOX500	5117/L	1	10,97
9	The breast P HARDOX500	5084/P	2,9	23,82
10	The breast L HARDOX500	5085/L	2,9	23,82
11	The short slade P HARDOX500	6004B/P	3,6	35,14
12	The short slade L HARDOX500	6005B/L	3,6	35,14
13	The long slade P HARDOX500	6002B/P	4,9	47,02
14	The long slade L HARDOX500	6003B/L	4,9	47,02
To the plough GOIZIN				
1	The chisel P HARDOX500	10104/P	1,6	12,76
2	The chisel L HARDOX500	10154/L	1,6	12,76
3	The share P HARDOX500	10400/P	6,6	55,09
4	The share L HARDOX500	10450/L	6,6	55,09
5	The share P HARDOX500	10733/P	0,9	10,83
6	The share L HARDOX500	10783/L	0,9	10,83
7	The share P HARDOX500	10732/P	1,2	13,43
8	The share L HARDOX500	10782/L	1,2	13,43
9	The breast P HARDOX500	10526/P	2,7	22,81
10	The breast L HARDOX500	10576/L	2,7	22,81
11	The breast P HARDOX500	11504/P	1,2	13,30
12	The breast L HARDOX500	11554/L	1,2	13,30
13	The breast P HARDOX500	11626/P	1,6	17,48
14	The breast L HARDOX500	11676/L	1,6	17,48
15	Back slat of moldboard P HARDOX450	10202/P	1,6	11,97
16	Back slat of moldboard L HARDOX450	10252/L	1,6	11,97
17	The slade P HARDOX500	10334/P	2,7	20,27
18	The slade L HARDOX500	10384/L	2,7	20,27
19	The slade P HARDOX500	10534/P	3,3	24,07
20	The slade L HARDOX500	10584/L	3,3	24,07
21	The lap P/L HARDOX500	10327/S	2,6	21,54
To the plough BONNEL				
1	The chisel P HARDOX500	13200074/P	1,9	16,46
2	The chisel L HARDOX500	13200075/L	1,9	16,46
3	The share P HARDOX500	13200005/P	8	65,51
4	The share L HARDOX500	13200006/L	8	65,51
5	The share P HARDOX500	13200008/P	7,1	56,90
6	The share L HARDOX500	13200009/L	7,1	56,90
7	The share P HARDOX500	13100147/P	1,7	17,10
8	The share L HARDOX500	13100148/L	1,7	17,10
9	The slade P/L HARDOX500	13100152/S	3,9	28,79
10	The lap P/L HARDOX500	5032020900/S	2,1	17,74
To the plough KARSTEN				
1	The chisel HARDOX500	S	4,8	43,08
2	The share R HARDOX500	P	1,2	13,43
3	The share L HARDOX500	L	1,2	13,43
To the Aggregate FARMET				
1	The share R HARDOX500	1738600020/P	2,3	18,75
2	The share L HARDOX500	1738600030/L	2,3	18,75
To the Aggregate HORSCH				
1	The beak of the coulter HARDOX500	34060850/S	1,8	15,20
To the Aggregate KONGSKILDE				
1	The beak of the coulter HARDOX500	101003120/S	1,8	15,20
The tillage aggregate				
1	The cultivation point 6x40x200		0,35	1,23
2	The cultivation point straight 6x40x210	3371000/S	0,35	1,23

3	The cultivation point straight 6x40x135		0,22	1,03
	The cultivator			
1	The cultivation point	1410/01006/S	0,45	1,47
	The cultivator russian KPC190			
1	The cultivation point	КПЦ 02.402, PK7	0,65	2,13
	Polish Spreader			
1	Spreader tine HARDOX450		1,35	11,13
	To Spreader LEBOULCH			
1	Knife HARDOX500		1,45	10,14
	To Disc harrow HORSCH			
1	Side plate P HARDOX450	310892/6/P	4,2	63,35
2	Side plate L HARDOX450	310892/6/L	4,2	63,35
3	Side plate P HARDOX500	310892/8/P	5,6	83,62
4	Side plate L HARDOX500	310892/8/L	5,6	83,62
	To Disc harrow AGROMASZ			
1	Scraper HARDOX450		0,3	3,80
	To Active harrow KUHN			
1	Scraper HARDOX450	52532130/S	0,2	3,82
	To Active harrow RAU			
1	Scraper HARDOX450		0,31	4,56
	To Active harrow BECKER			
1	The straight tooth HARDOX500		1	8,36
2	The bent tooth HARDOX500		1,2	11,91
	To Active harrow SICMA			
1	Scraper HARDOX450	ERS2500	0,4	4,56
	To Active harrow SULKY			
1	Scraper HARDOX450	AB720345/S	0,17	3,07
	To Active harrow AMAZONE			
1	Scraper HARDOX450	RE301	0,3	3,76
	To Harvester-thresher DRONNINGBORG			
1	Scythe guide HARDOX500		0,5	7,60
	To Harvester-thresher CASE			
1	Scraper HARDOX450	IH1440	3,3	25,86
	To The Beet combine HOLMER / ROPA			
1	The share R HARDOX500	1145004050/P	1,6	15,35
2	The share L HARDOX500	1145004051/L	1,6	15,35
3	The share R HARDOX500	1145010020/P	2,3	21,11
4	The share L HARDOX500	1145010021/L	2,3	21,11
5	The share R HARDOX500	1145019882/P	2,4	24,95
6	The share L HARDOX500	1145019883/L	2,4	24,95
	To Potato-combine harvester GRIMME			
1	The share P HARDOX450	08900029/P	1,6	20,38
2	The share L HARDOX450	08900030/L	1,6	20,38
3	The share P HARDOX450	08900031/P	1,4	18,81
4	The share L HARDOX450	08900032/L	1,4	18,81
5	The share HARDOX450	08900071/S	1,5	20,38
6	The share HARDOX450	08900270/S	1,4	20,38
7	The share P HARDOX450	08900354/P	2	21,94
8	The share L HARDOX450	08900355/L	2	21,94
9	The share P HARDOX450	08900357/P	2,5	26,64
10	The share L HARDOX450	08900358/L	2,5	26,64
11	The share P HARDOX450	08900456/P	2,7	28,21
12	The share L HARDOX450	08900457/L	2,7	28,21
13	The share P HARDOX450	08900463/P	2,5	26,65

14	The share L	HARDOX450	08900464/L	2,5	26,65
15	The share P	HARDOX450	08901439/P	2,6	43,88
16	The share L	HARDOX450	08901440/L	2,6	43,88
17	The share P	HARDOX450	08902490/P	3	31,91
18	The share L	HARDOX450	08902491/L	3	31,91
To Potato-combine harvester REEKE					
1	The share C	HARDOX500		2,5	37,30
2	The share P	HARDOX500		2,5	37,30
3	The share L	HARDOX500		2,5	37,30
To Corn-combine harvester STARR CPESAV					
1	Knife	HARDOX450		1,4	38,74
To Separator of stones REEKE					
1	The share C	HARDOX500		1,8	26,11
2	Edge 1	HARDOX500		0,35	8,06
3	Edge 2	HARDOX500		0,6	9,02
To Strewer REEKE					
1	The cultivation point		UN15632/S	6,7	69,11
To Feed cart STOLL					
1	The base of feed cart		2712-743X/S	5,4	38,38
To Soving-maschine KONGSKILDE					
1	Coulter disc	HARDOX450	MultiJet 3m	4,6	46,05
To Soving-maschine NORDSTEN					
1	Coulter disc	HARDOX450	KS3030	3,8	41,06
To Soving-maschine VREDO					
1	Coulter disc	HARDOX450	3000P161-01/S	2,4	31,47
2	Sceaper of coulter P	HARDOX450		0,13	7,60
3	Sceaper of coulter L	HARDOX450		0,13	7,60
To Soving aggregate KVERNELAND					
1	Sceaper of the shaft	HARDOX500	do Compact 3	0,4	4,31
To Soving-maschine KRAUSE					
1	Coulter disc	HARDOX450	5500	2,8	28,79
To Soving-maschine BECKER					
1	Coulter disc	HARDOX450	55412	1,2	21,11
To Soving-maschine MASCHIO Gaspardo					
1	Coulter disc	HARDOX450	13825091D373	2	30,70
2	Coulter disc	HARDOX450	13825091D373/4	3,3	38,01
3	Coulter disc	HARDOX450	13825091D280	1,2	26,86
To The tillage aggregate LELLY					
1	Scraper of the shaft	HARDOX450	1164527821/S	0,3	4,31
To Chaff-cutter CLAAS					
1	Cover	HARDOX450	682380/S	10,5	76,02
2	Cover	HARDOX450	762023/S	9,6	88,27
3	Cover	HARDOX450	763911/P	1,9	17,74
4	Cover	HARDOX450	763921/L	1,9	17,74
5	Side cover	HARDOX450		6,7	50,68
6	Plate collecting of cemper	HARDOX450		42	364,59
Chaff-cutter Z305					
1	Knife	HARDOX500		3	38,38
To Wrapper SIPMA					
1	Holder	HARDOX500	3600-040-160.10/S	3,5	55,17
To Baler KRONE					
1	Scraper	HARDOX450	280851/S	0,5	7,60
2	Scraper	HARDOX450	280852/S	0,9	17,74
To The trailer self-collecting KRONE					

1	Star of rotor HARDOX450	3349645/S	1,9	23,03
To The trailer self-collecting POTTINGER				
1	Star of rotor HARDOX500		3,3	51,17
To the Trailer self-collecting SCHUITEMAKER				
1	Knife HARDOX450	1252103/S 433999/S	0,76	23,03
Cutter of silage SPAWMECH				
1	Rectangular knife HARDOX500		0,8	15,35
2	Triangular knife HARDOX500		1,3	22,26
3	Half triangular knife P HARDOX500		0,6	12,66
4	Half triangular knife L HARDOX500		0,6	12,66
Cutter of silage KATY				
1	Long knife 1P HARDOX500		1,3	18,81
2	Long knife 1L HARDOX500		1,3	18,81
3	Long knife 2P HARDOX500		1,1	16,88
4	Long knife 2L HARDOX500		1,1	16,88
5	Triangular knife HARDOX500		1,2	21,87
6	Half triangular knife P HARDOX500		0,6	13,05
7	Half triangular knife L HARDOX500		0,6	13,05
Cutter of silage KREATEC				
1	The side-knife 1100 HARDOX500		5,1	63,35
2	The side-knife 1001 4o HARDOX500		4,6	69,08
3	The side-knife 1000 HARDOX500		4,6	63,35
4	The side-knife 925 3o HARDOX500		4,2	63,35
5	The side-knife 850 HARDOX500		3,9	49,89
6	Triangular knife 171,5 HARDOX500	S171,5	1,7	28,79
7	Triangular knife 220 HARDOX500	S220	1,9	36,46
8	Half triangular knife 171,5 P HARDOX500	P171,5	1,3	25,71
9	Half triangular knife 220 P HARDOX500	P220	1,6	32,24
10	Half triangular knife 171,5 L HARDOX500	L171,5	1,3	25,71
11	Half triangular knife 220 L HARDOX500	L220	1,6	32,24
Packomat FRANDENT				
1	Scraper 4mm HARDOX500	4mm	0,3	4,14
2	Scraper 6mm HARDOX500	6mm	0,4	5,37
To Strawchopper Teagle TOMAHAWK				
1	Knife jerking 1g HARDOX450	SC1012	0,5	21,11
2	Knife jerking 2g HARDOX450	SC1013	0,5	24,95
3	Rotor blade HARDOX500	SC1699	1,8	25,34
4	Holder HARDOX450			5,85
Bale Cutter SPAWTECH				
1	Knife HARDOX500	HP1	0,3	30,70
To Rototiller LECKRON				
1	Knife P/L HARDOX500	SIM100	0,5	19,31
To Rototiller SB				
1	Knife P HARDOX500	SB/P	0,9	19,65
2	Knife L HARDOX500	SB/L	0,9	19,65
To Rototiller FARMAX				
1	Coulter HARDOX500	DHP180 LHD	6,8	106,38
2	Coulter HARDOX500	LRPS300 LDHK	11,3	161,46
To Rototiller IMANTS				
1	The share S HARDOX500	S22A220B155	1,6	26,86
2	The share P HARDOX500	S22A220B200	3,5	57,57
3	The share L HARDOX500	S22A220B200	3,5	57,57
4	The share P HARDOX500	A250B210	3,4	57,57
5	The share L HARDOX500	A250B210	3,4	57,57

To Plantingmaschine BASRIJS				
1	Knife P HARDOX500		0,6	14,11
2	Knife L HARDOX500		0,6	14,11
To Formingmaschine SCAN STONE				
1	The share P HARDOX500	UN15633/P	1,6	16,15
2	The share L HARDOX500	UN15630/L	1,6	16,15
To Grubber LEMKEN				
1	The share R/L HARDOX500	3371686/S	6,8	85,48
2	The share R/L HARDOX500	3374340/S	6,5	54,95
To Grubber KONGSKILDE ECO				
1	Tooth HARDOX500		3	88,69
2	Lap HARDOX500		1,5	25,34
To Grubber UNIA Kret				
1	The chisel HARDOX500	GK020	8,4	94,98
2	Lap HARDOX500	Nakładka	1,2	12,35
Bolts and nuts				
1	Bolt M10x35 8,8		0,02	0,19
2	Bolt M10x35 10,9		0,02	0,29
3	Bolt M10x35 8,8 coulter		0,03	0,29
4	Bolt M10x50 8,8		0,04	0,29
5	Bolt M10x60 8,8		0,04	0,30
6	Bolt M12x35 8,8		0,03	0,38
7	Bolt M12x40 8,8		0,04	0,38
8	Bolt M12x50 10,9		0,05	0,38
9	Bolt M12x70 12,9		0,06	0,53
10	Bolt M12x90 12,9		0,09	0,76
11	Bolt M12x110 10,9 with nut		0,1	1,71
12	Bolt M16x50 8,8 with nut		0,08	0,68
13	Bolt M16x110 8,8 with nut		0,18	1,14
14	Bolt M20x60 8,8 with nut		0,21	1,04
15	Bolt M20x90 8,8 with nut		0,28	1,24
16	Bolt M22x70 10,9 with nut		0,31	3,80
17	Bolt M22x90 10,9 with nut		0,36	4,18
18	Bolt oval M10x34 12,9 with nut		0,02	0,47
19	Bolt oval M12x34 12,9 with nut		0,04	0,36
20	Bolt oval M12x40 12,9 with nut		0,05	0,42
21	Bolt oval M12x45 12,9 with nut		0,05	0,57
22	Bolt oval M12x55 12,9 with nut		0,06	0,57
23	Bolt oval M12x90 12,9 with nut		0,08	0,95
24	Bolt oval M14x34 12,9 with nut		0,06	0,42
25	Bolt oval 35149 M14x34 12,9 with nut		0,06	1,90
26	Bolt oval M14x38 12,9 with nut		0,06	0,57
27	Bolt oval M14x45 12,9 with nut		0,07	0,57
28	Bolt oval M14x60 10,9 with nut		0,08	0,57
29	Bolt oval M16x50 12,9 with nut		0,1	0,95
30	Bolt oval M16x75 12,9 with nut		0,15	1,14
31	Bolt oval M16x85 12,9 with nut		0,16	1,33
32	Bolt oval M18x90 10,9 with nut		0,22	1,33
33	Bolt oval M20x50 10,9 with nut		0,18	1,52
34	Bolt oval M20x90 10,9 with nut		0,27	2,54
35	Bolt to breast M10/35 10,9		0,02	0,25
36	Bolt to moldboard M12x35		0,03	0,38
37	Bolt to moldboard M12x50		0,04	0,38
38	Bolt to coulter M10/30 12,9		0,02	0,25

39	Screw conical M12/65 10,9 with nut		0,07	0,57
40	Screw conical M14/60 10,9 with nut		0,09	0,95
41	Screw conical M16/60 10,9 with nut		0,12	1,14
42	Screw conical M18/70 10,9 with nut		0,13	2,00
43	Screw conical M20/50 10,9 with nut		0,18	1,34
44	Screw conical M20/70 10,9 with nut		0,17	2,09
45	Screw conical M20/70 10,9 with nut		0,21	2,47
46	Screw conical M24/70 10,9 with nut		0,3	3,80
47	Screw conical M24/90 10,9 with nut		0,4	4,56
48	Nut M10 5,8		0,01	0,05
49	Nut M10 8,8		0,01	0,06
50	Nut M12 5,8		0,015	0,07
51	Nut M12 8,8		0,015	0,10
52	Pillow 12		0,005	0,10

The builder's machines

1	Podeszwa stopy BOMAG BT65 HARDOX450	BT65	4,5	41,37
2	Podeszwa stopy BOMAG BT60 HARDOX450	BT60	3,7	34,48
3	Podeszwa stopy BELLE RTX68 HARDOX450	RTX68	4,6	45,97
5	The knife 75mm to MAKITA BBA520 HARDOX500	Ø200	0,14	8,63
6	The knife 100mm to MAKITA BBA520 HARDOX500	Ø250	0,19	9,19

Abrasion resistant steel plates 50HRC

1	Abrasion resistant steel plates	2000/6000/8-20	1	3,75
---	--	----------------	---	-------------

The original catalogue numbers are stated exclusively for comparative purposes. The stated products and their prices are presented exclusively for your guidance and they do not constitute an offer as defined in the commercial law. ZPL Stankiewicz does not assume any liability for the mistakes in the publication and reserves the right to change the prices without prior notice.

Price rebates

Seasonal

The month	Rebate
January	2%
February	1%
March	-
April	-
May	3%
June	2%
July	1%
August	-
September	-
October	-
November	-
December	3%

For the payment with the cash 1%

The rebate for wholesale-customers ~ fix severally

Kurs zakupu dewiz w NBP z dnia **4,28**

All rebates 0